
IOT practical 3

TITLE:- Draw and interfacing diagram of Temperature sensor (LM35) with Arduino and write a program to display temperature on serial monitor



• Code
int sensorValue = 0;

void setup()
{
 pinMode(A0, INPUT);
 Serial.begin(9600);
}

void loop()
{
 sensorValue = ((analogRead(A0)/1023.00)*100);
 Serial.println("Temperature");
 Serial.println(sensorValue); delay(100);
}