

A diagram of a rectangular board with rounded corners. Inside the board, there are two 'x' marks representing drill holes, positioned horizontally near the top center.

Drill Map:
× 0.650mm / 0.0256" (2 holes) (not plated)