

A diagram showing two 'x' marks representing drill holes, positioned horizontally and centered within a large rectangular frame with rounded corners.

Drill Map:  
× 0.650mm / 0.0256" (2 holes) (not plated)