



ELECTRICAL RESEARCH AND DEVELOPMENT ASSOCIATION

(Accredited by the National Accreditation Board for Testing and Calibration Laboratories, Govt. of India) ERDA Road, Makarpura Industrial Estate, Vadodara-390 010, India.

EPABX : +91 (0265) 2642942, 2642964, 2642377, 3043128 / 29 / 30 / 31 / 33

: +91 (0265) 2638382 Fax E-mail : erda@erda.org Web : http://www.erda.org



ULR-TC538919000009684F

TEST REPORT

5	r	IE	E	ı	:	T	UF	4

NAME & ADDRI	ESS OF CUSTOMER	TEST REPO	RT NO.: RP-1	819-050161	
		DATE	: 26.0	3.2019	
PLANETRIC POWER LLP MNO-3076		CUSTOMER REF. NO.: NIL DATE: 14.03.2019			
Pune- Nagar Roa	• • •	DATE OF RECI	SAMPLE EIPT	DATE OF TESTING	
Tal-Haveli, Dist- Maharashtra-412	•	18.03	.2019	22.03.2019 to 25.03.2019	
SAMPLE DESC	RIPTION	SAMPLE ID	ENTIFICATION ENTIF	ON	
CURRENT TRANS		SR. NO.	: 55/2019		
RATIO : BURDEN : CLASS : I.L. :	ETRIC POWER LLP 3000/5 A 15 VA 5P10 0.66/3.0 kV 50 Hz. LATION: B	ERDA SAMP ERDA-00307	PLE CODE NO 138). :	
TEST DETAILS	& TEST SPECIFICATION ARE AS	S PER SHEET	NO. 2 OF 4.		
ENCLOSURE	: 1) Photographs of Test sample 2) DRAWING NO. : 1) LTCT009/ 2) A4 LTCT0		,	sheet: 1 of 1)	
NOTE	: Testing was carried out as per request.	standard IS 2	705:1992 as	per customer's	
REMARK	: The sample conforms to the re standard as mentioned in tests				
nij	À.		Bli	121	
PREPARED BY	CHECKED BY	,		VED BY PATEL)	

ERDA, Vadodara.

2. This report cannot be reproduced in part under any circumstances.

3. Publication of this report requires prior permission in writing from Director, ERDA.

4. Only tests asked for by the customer have been carried out.

5. In case of any dispute, Vadodara will be the exclusive jurisdiction & shall be construed as where the cause has arised.

Caution: ERDA is not responsible for the authenticity of photocopied or reproduced test reports, ERDA provides support to customers for verification of the authenticity of test reports issued by ERDA.







ELECTRICAL RESEARCH AND DEVELOPMENT ASSOCIATION

(Accredited by the National Accreditation Board for Testing and Calibration Laboratories, Govt. of India) ERDA Road, Makarpura Industrial Estate, Vadodara-390 010, India.

EPABX : +91 (0265) 2642942, 2642964, 2642377, 3043128 / 29 / 30 / 31 / 33

Fax : +91 (0265) 2638382 E-mail : erda@erda.org Web : http://www.erda.org



ULR-TC538919000009684F

TEST REPORT NO.: RP-1819-050161 DATE: 26.03.2019 SHEET: 2 OF 4

TEST DETAILS & TEST SPECIFICATION:

Sr. No.	TESTS	REFERENCE STANDARD
1.	Verification of terminal marking and polarity.	Cl. No. 9.2 of IS 2705 (Part 1): 1992
2.	Power frequency dry withstand test on primary winding.	Cl. No. 9.3 of IS 2705 (Part 1): 1992
3.	Power frequency dry withstand test on secondary winding.	Cl. No. 9.4 of IS 2705 (Part 1): 1992
4.	Over voltage inter-turn test.	Cl. No. 9.5 of IS 2705 (Part 1): 1992
5.	Determination of errors according to the requirements of the appropriate accuracy class.	Cl. No. 7.2.1 of IS 2705 (Part 3): 1992
6.	Composite error test	Cl. No. 7.2.2 of IS 2705 (Part 3): 1992

NOUL

PREPARED BY

CHECKED BY

C 2744720





ELECTRICAL RESEARCH AND DEVELOPMENT ASSOCIATION

(Accredited by the National Accreditation Board for Testing and Calibration Laboratories, Govt. of India) ERDA Road, Makarpura Industrial Estate, Vadodara-390 010, India.

EPABX : +91 (0265) 2642942, 2642964, 2642377, 3043128 / 29 / 30 / 31 / 33

Fax : +91 (0265) 2638382



Certificate No.: TC-5389

E-mail : erda@erda.org
Web : http://www.erda.org

ULR-TC538919000009684F

TEST REPORT NO.: RP-1819-050161 DATE: 26.03.2019 SHEET: 3 OF 4

TEST RESULTS:

1. Verification of terminal marking and polarity.

(Cl. No. 9.2 of IS 2705 (Part 1): 1992)

Primary winding terminals : P1-P2

Secondary windings terminals: S1-S2

Terminal marking & polarity was found Ok.

Terminal marking was found marked clearly & indelibly.

REMARK: Conforms

2. Power frequency dry withstand test on primary winding.

(Cl. No. 9.3 of IS 2705 (Part 1): 1992)

The power frequency voltage of 3 kV (rms) was applied between the primary winding (i.e. Copper Foil) & earth, for one minute duration. The secondary winding terminals were connected together to earth. The sample withstood the test voltage without any disruptive discharge.

REMARK: Conforms

3. Power frequency dry withstand test on secondary winding.

(Cl. No. 9.4 of IS 2705 (Part 1): 1992)

The power frequency voltage of 3 kV (rms) was applied between the secondary windings terminals (all) connected together and the earth. The primary winding (i.e. Copper Foil) was connected to the earth. The test voltage was applied for one minute.

There was no disruptive discharge observed. The sample withstood the test voltage satisfactorily.

REMARK: Conforms

4. Over voltage inter-turn test. (Cl. No. 9.5 of IS 2705 (Part 1): 1992)

With secondary winding connected to oscilloscope, a substantially sinusoidal current at 50 Hz frequency & of rms value equal to rated primary current (i.e. 3000 A) was applied for 60 seconds to the primary winding. The sample withstood the test voltage for secondary terminals S1-S2 of secondary side for 60 seconds.

REMARK: Conforms

nacy

PREPARED BY

CHECKED BY







ELECTRICAL RESEARCH AND DEVELOPMENT ASSOCIATION

(Accredited by the National Accreditation Board for Testing and Calibration Laboratories, Govt. of India)
ERDA Road, Makarpura Industrial Estate, Vadodara-390 010, India.

EPABX : +91 (0265) 2642942, 2642964, 2642377, 3043128 / 29 / 30 / 31 / 33

Fax ; +91 (0265) 2638382 E-mail : erda@erda.org Web : http://www.erda.org



ULR-TC538919000009684F

TEST REPORT NO.: RP-1819-050161 DATE: 26.03.2019 SHEET: 4 OF 4

5. <u>Determination of errors according to the requirements of the appropriate accuracy class.</u> (Cl. No. 7.2.2 of IS 2705 (Part 3): 1992)

CLASS: 5P, BURDEN: 15 VA @ 0.8 Lag. P. F.

RATIO	Secondary winding	% OF RATED	RATIO ERROR	PHASE ANGLE
	terminals	CURRENT	IN %	ERROR IN MIN.
3000/5 A	S1-S2	100	-0.263	2.63

REMARK: Conforms

6. Composite error test. (Cl. No. 7.2.2 of IS 2705 (Part 3): 1992)

Secondary winding terminals : S1-S2

RATIO : 3000/5 A

Rct@75°C : 1.1736Ω

SLV Computed : 84.62 V

Excitation Current measured : 34.5 mA

Composite Error : 0.069 %

REMARK: Conforms

ney

PREPARED BY CHECKED BY







ELECTRICAL RESEARCH AND DEVELOPMENT ASSOCIATION

(Accredited by the National Accreditation Board for Testing and Calibration Laboratories, Govt. of India) ERDA Road, Makarpura Industrial Estate, Vadodara-390 010, India.

EPABX : +91 (0265) 2642942, 2642964, 2642377, 3043128 / 29 / 30 / 31 / 33

Fax : +91 (0265) 2638382 E-mail : erda@erda.org

Web : http://www.erda.org





ULR-TC538919000009684F

Annexure-I

TEST REPORT NO.: RP-1819-050161 DATE: 26.03.2019 SHEET: 1 OF 1

PHOTOGRAPHS OF TEST SAMPLE



PREPARED BY

CHECKED BY



ATION 609/2018 AS CARDISTANS ASE to pure titled through blatco I COAL SON TO TALO T W. ETHI 20110 81/2/18 26' NO' : -- 310M PLANTING POSTE ED. RINE TIMEST THIESE (4) Sk-Ac. 6 RATING & DIAGRAM PLATE PLANETIC POWER LP PUNE-12207 INCH CLASS: 52010 CURRENT IRANSFORMER SR. NO. 55/2019 MADE TO 1.5.S. 2705/1992 UNE VOITS: 1.1, 0.66/3.0 KV CALGARDAN / 12/71 Flat. Pare: 26.03.2019 MAN A MAN COMM P-1819-050161 3300 A V.E. Receipted T. 77 CLASS OF INSULATION: 83 Total Medal May 23. 14th 14th RATIO: 3000/SA FREC, SO HZ SECTION OF THE SECTIO Actor Nove Statement of the Company to so muc by tender CHEST CONTRACTOR 54 MEN 24

<u>.</u>|

