Εθνικό Μετσόβιο Πολυτεχνείο Σχολή Ηλεκτρολόγων Μηχ. Και Μηχ. Υπολογιστών Εργαστήριο Μικροϋπολογιστών , 7ο εξάμηνο - Ροή Υ Ακαδημαϊκή Περίοδος : 2011-2012



# $3^{\eta} \Sigma EIPA A \Sigma KH \Sigma E \Omega N$

Ομάδα: C16

Γερακάρης Βασίλης Α.Μ.: 03108092

Διβόλης Αλέξανδρος Α.Μ.: 03107238

Ίεντσεκ Στέργιος Α.Μ.: 03108690

## Εισαγωγικά

Σε αυτήν την σειρά ασκήσεων χρησιμοποιήθηκαν κάποιες μακροεντολές ώστε ο κώδικας να είναι πιο κατανοητός και ο προγραμματισμός εύκολος. Παρακάτω βλέπουμε το αρχείο **MACROS.TXT:** 

```
MACROS.txt - Notepad
File Edit Format View Help
;This macro change registers AH,AL
READ MACRO
    MOV AH, 8
INT 21H
ENDM
;This macro changes registers AH,DL
PRINT MACRO CHAR
        PUSH AX
        PUSH DX
        MOV DL, CHAR
        MOV AH, 02H
        INT 21H
        POP DX
        POP AX
ENDM
;This macro change registers AH,DX
PRINT_STRING MACRO STRING
        MOV DX,OFFSET STRING ; Assume that string is a variable or constant, NOT an address
        MOV AH, 09H
        INT 21H
        POP DX
        POP AX
ENDM
PRINT_NUM MACRO CHAR
        MOV DL, CHAR
        ADD DL, 30H
MOV AH, 2
INT 21H
ENDM
PAUSE MACRO
                        ; <=>MOV DX, OFFSET PKEY; GIVES THE OFFSET OF PKEY TO DX
    PUSH AX
    PUSH DX
    LEA DX, PKEY
                        ; OUTPUT STRING AT DS:DX
    MOV AH, 9
                         WAIT FOR PRESSING OF A KEY
    INT 21H
    MOV AH, 8
INT 21H
                        ; WITHOUT ECHO->8
    PRINT OAH
    PRINT ODH
    POP DX
    POP AX
ENDM
EXIT MACRO
        MOV AH, 4CH
        INT 21H
ENDM
```

### Ασκηση i

Στην άσκηση αυτή εισάγουμε έναν 10bit δυαδικό αριθμό τον οποίο μετατρέπουμε σε δεκαδικό. Κατά την εισαγωγή αριθμού δεχόμαστε τιμές μόνο 0 και 1, τα οποία και τυπώνονται στην οθόνη ή 'Q' ή 'q' για έξοδο. Σε περίπτωση που πατηθεί οποιοδήποτε άλλο πλήκτρο το πρόγραμμα το αγνοεί και αναμένει το πάτημα ενός έγκυρου πλήκτρου. Οι ρουτίνες που υλοποιήθηκαν είναι η BIN\_10BIT\_IN η οποία εισάγει τον 10bit αριθμό και τον αποθηκεύει στον καταχωρητή DX ή βγαίνει σε περίπτωση που πατηθεί το 'q' ή 'Q', καθώς και η PRINT\_DEC, η οποία δέχεται σαν είσοδο το περιεχόμενο του καταχωρητή DX και τον τυπώνει σε δεκαδική μορφή. Ο κώδικας φαίνεται παρακάτω:

```
INCLUDE MACROS.TXT
STACK SEG SEGMENT STACK
 DW 128 DUP(?)
ENDS
DATA SEG SEGMENT
 PKEY DB "press any key to restart or 'Q' to exit!..$"
 IN_MSG DB "GIVE A 10-BIT BINARY NUMBER: $"
 OUT MSG DB "DECIMAL: $"
 LINE DB 0AH,0DH,"$"
ENDS
CODE SEG SEGMENT
 ASSUME CS:CODE_SEG,SS:STACK_SEG,DS:DATA_SEG,ES:DATA_SEG
MAIN PROC FAR
 ;SET SEGMENT REGISTERS
 MOV AX, DATA SEG
 MOV DS,AX
 MOV ES, AX
;=-=-=-=-----CODE-=-=-=-
START:
 PRINT STRING IN MSG
 CALL BIN 10BIT IN :DX<-000000 b9 b8 b7 b6 b5 b4 b3 b2 b1 b0
 PRINT_STRING LINE
 PRINT STRING OUT MSG
 CALL PRINT_DEC
                  ;Must have in DX the number
 PRINT_STRING LINE
 PRINT STRING PKEY
 READ
 CMP AL,'q'
 JE EXODOS
 CMP AL,'O'
 JE EXODOS
 PRINT STRING LINE
 JMP START
EXODOS:
 EXIT
MAIN ENDP
;-----ROUTINES-----
```

```
BIN_10BIT_IN PROC NEAR
  MOV DX,0
  MOV CX,10
IGNORE:
             ;Read changes AX: puts input in AL and gives DOS function code with AH
  READ
         CMP AL,'q'
         JE EXODOS
         CMP AL,'O'
         JE EXODOS
  CMP AL,30H
  JL IGNORE
  CMP AL,31H
  JG IGNORE
               ;If we pass we have 0 or 1
  PRINT AL
               ;AX<-00000000 0000000(0 or 1)
  SUB AL,30H
  MOV AH,0
  ROL DX,1
  ADD DX,AX
  LOOP IGNORE
                 ;loop for 10 times to import 10 bits
  RET
BIN_10BIT_IN ENDP
PRINT_DEC PROC NEAR
; PUSH AX
  PUSH BX
; PUSH CX
; PUSH DX
  MOV AX,DX ;Put number in AX
  MOV BX,10 ;Put the divisor in BX
  MOV CX,0 ;Counts the number of decimal digits
AGAIN:
  MOV DX,0
  DIV BX
           ;quotient in AX and remainder in DX
  PUSH DX
  INC CX
  CMP AX,0 ;Check if quotient = 0 (all digits stored in stack)
  JNE AGAIN
PRINT_LOOP:
  POP DX
  PRINT_NUM DL
 LOOP PRINT_LOOP
  POP DX
; POP CX
; POP BX
; POP AX
  RET
PRINT_DEC ENDP
CODE_SEG ENDS
END MAIN
```

### Ασκηση ii

Μας ζητείται να εισάγουμε έναν τετραψήφιο δεκαδικό αριθμό ώστε να τον τυπώσουμε στη συνέχεια σε δεκαεξαδική μορφή. Εισάγουμε τον δεκαδικό αριθμό με την βοήθεια της ρουτίνας **DEC\_4DIG\_IN**, η οποία ελέγχει εαν το πλήκτρο που πατήθηκε δίνει αποδεκτή τιμή (0-9 δεκαδικό), αν ναι το τυπώνει στην οθόνη, πολλαπλασιάζει την τρέχουσα τιμή του καταχωρητή στον οποίο αποθηκεύεται ο αριθμός με το 10 (εφόσον το ψηφίο που μόλις εισάχθηκε είναι πολλαπλάσιο μίας δύναμης του 10 μικρότερης κατά 1 από τον ήδη υπάρχοντα αριθμό) και προσθέτει τον αριθμό. Μόλις εισαχθούν και τα 4 ψηφία αναμένεται η πίεση του πλήκτρου **ENTER** και μόνο. Με την βοήθεια της υπορουτίνας **PRINT\_HEX** τυπώνεται ο αριθμός που βρίσκεται στον **DX** καταχωρητή σε 16αδική μορφή. Στη συνέχεια παρατίθεται ο κώδικας:

```
INCLUDE MACROS.TXT
STACK SEG SEGMENT STACK
 DW 128 DUP(?)
ENDS
DATA_SEG SEGMENT
 PKEY DB "press any key to restart or 'Q' to exit!..$"
 IN MSG DB "GIVE FOUR NUMBERS: $"
 OUT MSG DB "HEX = $"
       ENTER MSG DB "PLEASE PRESS ENTER!$"
 LINE DB 0AH.0DH."$"
ENDS
CODE SEG SEGMENT
 ASSUME CS:CODE_SEG,SS:STACK_SEG,DS:DATA_SEG,ES:DATA_SEG
MAIN PROC FAR
 SET SEGMENT REGISTERS
 MOV AX, DATA_SEG
 MOV DS, AX
 MOV ES, AX
START:
 PRINT STRING IN MSG
 CALL DEC_4DIG_IN ;DX has the inputed number!
NOT ENTER:
       READ
       CMP AL,0DH
       JNE NOT ENTER
 PRINT_STRING LINE
       PRINT_STRING ENTER_MSG
       PRINT STRING LINE
 PRINT STRING OUT MSG
 CALL PRINT HEX
                  :Must have in DX the number
 PRINT STRING LINE
 PRINT_STRING PKEY
 READ
 CMP AL,'q'
 JE EXODOS
 CMP AL,'Q'
```

```
JE EXODOS
 PRINT_STRING LINE
 JMP START
EXODOS:
 EXIT
MAIN ENDP
;------ROUTINES-----
DEC_4DIG_IN PROC NEAR
  MOV DX,0
        MOV BH,0
  MOV CX.4
IGNORE:
 READ
             ;Read changes AX: puts input in AL and gives DOS function code with AH
         CMP AL,'q'
         JE EXODOS
         CMP AL,'Q'
         JE EXODOS
  CMP AL,30H
  JL IGNORE
  CMP AL,39H
  JG IGNORE
               ;If we pass we have accepted value
                           ;We have read withouth echo
 PRINT AL
  SUB AL,30H
              ;AX<-(0-9)
         MOV BL,AL
                                    ;BX<-00000000 (AL) the new decimal digit
         MOV AX,DX
                                    ;put the number in AX
         MOV DX,10
                                    ;DX<-10 multiplier
                                    ;AX*DX: Result is returned to DX-AX, but it can't be >9999, so it fits
         MUL DX
in AX
         MOV DX,AX
         ADD DX,BX
                                    ;Add NEW digit
 LOOP IGNORE ;loop for 10 times to import 10 bits
                           ;Finally we have the number in DX
  RET
DEC_4DIG_IN ENDP
PRINT_HEX PROC NEAR
; PUSH AX
; PUSH BX
; PUSH CX
 PUSH DX
  MOV AX,DX ;Put number in AX
  MOV BX,16 ;Put the divisor in BX
  MOV CX,0 ;Counts the number of decimal digits
AGAIN:
 MOV DX,0
           ;quotient in AX and remainder in DX
 DIV BX
 PUSH DX
  INC CX
 CMP AX,0 ;Check if quotient = 0 (all digits stored in stack)
 JNE AGAIN
PRINT LOOP:
  POP DX
  CMP DL,9
                  ;i know that in char is something between 00000000 and 00001111
         JBE DEC_DEC
                           ;if A<=9 jump to DEC_DEC
         ADD DL,07H; we add total 37H, if we have something A-F
DEC_DEC:
         ADD DL,30H
         MOV AH,02H
```

```
INT 21H ;To print the DL LOOP PRINT_LOOP; POP DX; POP CX; POP BX; POP AX RET PRINT_HEX ENDP

CODE_SEG ENDS

END MAIN
```

### Ασκηση iii

**INCLUDE MACROS.TXT** 

Στην άσκηση αυτή υλοποιούμε πρόγραμμα κατά το οποίο εισάγονται 20 (το πολύ) αλφαριθμητικοί χαρακτήρες (μόνο λατινικά γράμματα) και στη συνέχεια τυπώνονται με την σειρά εισαγωγής, όμως ανά είδος: **ΑΡΙΘΜΟΙ – ΠΕΖΟΙ ΧΑΡΑΚΤΗΡΕΣ – ΚΕΦΑΛΑΙΟΙ ΧΑΡΑΚΤΗΡΕΣ.** Πιέζοντας το **ENTER** ανά πάσα στιγμή δηλώνουμε τερματισμό της εισαγωγής χαρακτήρων και το πρόγραμμα τυπώνει την επιθυμητή έξοδο. Αν εισαχθούν και οι 20 χαρακτήρες αναμένεται η πίεση του πλήκτρου **ENTER** ώστε να συνεχίσει το πρόγραμμα. Αν πατηθεί κατά την είσοδο το πλήκτρο '/' το πρόγραμμα τερματίζει.

Η είσοδος των δεδομένων πραγματοποιείται με την ρουτίνα INPUT\_ROUTINE. Εκμεταλλευόμαστε το γεγονός ότι μπορούμε να έχουμε άμεσο έλεγχο κατά την πίεση ενός πλήκτρου, οπότε εφόσον εισαχθεί αποδεκτή τιμή ("0-9", "a-z", "A-Z"), αυτή αποθηκεύεται στον κατάλληλο πίνακα, NUM\_TABLE αν είναι αριθμός, LOWER\_TABLE αν είναι μικρός, ή UPPER\_TABLE αν είναι κεφαλαίος χαρακτήρας, με την ταυτόχρονη αύξηση του αντίστοιχου μετρητή (NUM\_COUNTER, LOWER\_COUNTER, UPPER\_COUNTER), ο οποίος κρατάει κάθε φορά το πλήθος των εγεγραμμένων χαρακτήρων στον αντίστοιχο πίνακα.

Με την βοήθεια της ρουτίνας **OUTPUT\_ROUTINE** τυπώνουμε με την σειρά τους τρείς πίνακες, ώστε να έχουμε το επιθυμητό αποτέλεσμα. Εντοπίζουμε το πρώτο στοιχείο του κάθε πίνακα με την βοήθεια της εντολής **MOV BX,OFFSET X\_TABLE** και αφού τυπώσουμε το στοιχείο του πίνακα αυξάνουμε κατά 1 τον καταχωρητή BX με **INC BX** ώστε να εντοπίσουμε το επόμενο στοιχείο του πίνακα (λόγω της ανά byte διευθυνσιοδότησης της μνήμης και του ότι κάθε στοιχείο είναι ένα byte. Αν π.χ. έπρεπε να εντοπίσουμε λέξεις θα προσθέταμε 2 κάθε φορά). Σε περίπτωση που δεν έχει εισαχθεί κάποιου είδους χαρακτήρας δεν τυπώνεται κάποιος χαρακτήρας αυτού του είδους (ελέγχοντας τον μετρητή του αντίστοιχου πίνακα).

Η λειτουργία του προγράμματος γίνεται πιο σαφής από τον παρακάτω κώδικα:

```
STACK_SEG SEGMENT STACK
DW 128 DUP(?)
ENDS

DATA_SEG SEGMENT
ENTAILMENT DB " => $"
LINE DB 0AH,0DH,"$"
INPUT_MSG DB "GIVE 20 CHARACTERS (Latin characters,numbers,spaces,/ for exit)",0AH,0DH,"$"
GIVE_MSG DB "GIVE AND PRESS ENTER:$"
NUM_TABLE DB 20 DUP(?)
LOWER_TABLE DB 20 DUP(?)
```


```
UPPER_TABLE DB 20 DUP(?)
       NUM COUNTER DW 0
       LOWER_COUNTER DW 0
       UPPER COUNTER DW 0
       INDEX DW 0
ENDS
CODE SEG SEGMENT
 ASSUME CS:CODE_SEG,SS:STACK_SEG,DS:DATA_SEG,ES:DATA_SEG
MAIN PROC FAR
 SET SEGMENT REGISTERS
 MOV AX, DATA_SEG
 MOV DS,AX
 MOV ES, AX
START:
 PRINT_STRING INPUT_MSG
 PRINT_STRING GIVE_MSG
 CALL INPUT_ROUTINE
       CALL OUTPUT_ROUTINE
       PRINT_STRING LINE
       MOV LOWER COUNTER,0
                              ;Resetting Counters for new input
       MOV UPPER_COUNTER,0
       MOV NUM_COUNTER,0
 JMP START
EXODOS:
 EXIT
MAIN ENDP
;-----ROUTINES-----
OUTPUT_ROUTINE PROC NEAR
       MOV CX, NUM_COUNTER
       CMP CX,0
       JE LOWER_START
                           ;Table is empty -> nothing to print
       MOV BX,OFFSET NUM TABLE ;The start address of NUM TABLE->Address of first data
NUM PRINT:
       MOV AL,DS:[BX]
       PRINT AL
       INC BX
                      ;BX+=1 to locate next data (1Byte-data)
       LOOP NUM PRINT
                         ;Do this NUM COUNTER times
       PRINT ''
LOWER_START:
                    ;Do the same for the other two tables
       MOV CX,LOWER_COUNTER
       CMP CX,0
       JE UPPER_START
       MOV BX,OFFSET LOWER_TABLE
LOWER PRINT:
       MOV AL,DS:[BX]
       PRINT AL
       INC BX
       LOOP LOWER_PRINT
       PRINT ''
UPPER_START:
       MOV CX, UPPER_COUNTER
       CMP CX,0
       JE PRINT_EJECT
       MOV BX, OFFSET UPPER_TABLE
UPPER PRINT:
```

```
MOV AL,DS:[BX]
        PRINT AL
        INC BX
        LOOP UPPER PRINT
PRINT_EJECT:
        RET
OUTPUT_ROUTINE ENDP
INPUT_ROUTINE PROC NEAR
        PUSH DX
        PUSH BX
        PUSH CX
 MOV DX,0
                 ;DH->Counter of Nums
        MOV BX,0
                          ;BX->Counter of Uppercase,
        MOV BP,0;BP->Counter of Lowercase
  MOV CX,20
                 ;Counter of maximum number of characters inputed
INPUT LOOP:
 READ
             ;Read changes AX: puts input in AL and gives DOS function code with AH
        CMP AL,0DH
                                   ;ODH = ENTER
        JE INPUT_END
        CMP AL,20H
                                   ;20H = SPACE
        JE SPACE LOOP
        CMP AL,2FH
                                   ;2FH = '/'
        JE EXODOS
  CMP AL.30H
 JL INPUT_LOOP
  CMP AL,39H
  JG UPPER CHECK ; If we pass we have 0-9 value
        PRINT AL
                          ;We have read withouth echo
NUM_INPUT:
        MOV BX, OFFSET NUM TABLE
        ADD BX, NUM_COUNTER
        MOV [BX],AL
                                   ;Move Char in Num_Table
        INC NUM COUNTER
                                   ;Increase num-counter
        JMP ENDING_LOOP
UPPER CHECK:
        CMP AL,41H
  JL INPUT LOOP
  CMP AL,5AH
  JG LOWER_CHECK ; If we pass we have A-Z value
        PRINT AL
                          ;We have read withouth echo
UPPER_INPUT:
        MOV BX, OFFSET UPPER_TABLE
        ADD BX,UPPER_COUNTER
        MOV [BX],AL
                                   ;Move Char in Num_Table
        INC UPPER COUNTER
                                   ;Increase upper-counter
        JMP ENDING LOOP
LOWER_CHECK:
        CMP AL,61H
  JL INPUT LOOP
  CMP AL,7AH
 JG INPUT_LOOP ;If we pass we have a-z value
        PRINT AL
                          ;We have read withouth echo
LOWER_INPUT:
        MOV BX,OFFSET LOWER_TABLE
        ADD BX,LOWER_COUNTER
        MOV [BX],AL
                                            ;Move Char in Num_Table
```

```
INC LOWER_COUNTER
                                 ;Increase upper-counter
ENDING LOOP:
        LOOP INPUT_LOOP
ENTER_LOOP:
        READ
        CMP AL,0DH
                                 ;ODH = ENTER
        JNE ENTER_LOOP
INPUT_END:
        PRINT_STRING ENTAILMENT
SPACE_LOOP:
        PRINT ''
        JMP ENDING LOOP
        POP CX
        POP BX
        POP DX
INPUT_ROUTINE ENDP
CODE_SEG ENDS
END MAIN
```

#### Ασκηση iv

Στην άσκηση αυτή μας ζητείται να πραγματοποιήσουμε πολλαπλασιασμό δύο 32bits αριθμών οι οποίοι εισάγονται από το πληκτρολόγιο, οπότε και προκύπτει αποτέλεσμα 64 bits. Αν χωρίσουμε τον κάθε 32bit αριθμό σε δύο 16bit μέρη (αφού μπορούμε να κάνουμε πολλ/σμο μεταξύ 16bit αριθμών). Στο παρακάτω σχήμα παρατηρούμε τους επιμέρους πολλαπλασιασμούς που πρέπει να γίνουν, καθώς και τις αντίστοιχες προσθέσεις.



Παρατηρούμε λοιπόν ότι πρέπει να προσθέσουμε τα εξής, ώστε να έχουμε το επιθυμητό αποτέλεσμα:  $RESULT = (X0\times Y0) + (X0\times Y1\times 2^{16}) + (X1\times Y0\times 2^{16}) + (X1\times Y1\times 2^{32}).$ Οι πολλαπλασιασμοί με τις δυνάμεις του 2 (16 και 32) φαίνεται με αριστερή ολίσθηση στο σχήμα.

Οι μεταβλητές που χρησιμοποιήθηκαν είναι αυτές που φαίνονται μέσα στα πεδία των **A**, **B**, **C**, **D**, **RESULT** και έχουν μέγεθος λέξης ( $1W = 2B \rightarrow 16$ bits). Η συλλογιστική της υλοποίησης φαίνεται παρακάτω και αφορά στην εύρεση των **RES\_0** εως **RES\_3**, με αρχικοποιημένο κρατούμενο **Carry** = **0**. Όπου Carry και Temporary καταχωρητές που χρησιμοποιούνται για αυτήν την δουλειά (βλέπε κώδικα).

- $RES_0 = A_LOW$
- $RES_1 = A_HIGH + B_LOW + C_LOW$ 
  - o Temporary =  $A_HIGH + B_LOW$ 
    - If (Cflag==1) Carry= Carry + 1
  - o  $RES_1 = Temporary + C_LOW$ 
    - If (Cflag==1) Carry= Carry + 1
- $RES_2 = B_HIGH + C_HIGH + D_LOW + Carry$ 
  - o Temporary = B\_HIGH + Carry, Carry = 0
    - If (Cflag==1) Carry= Carry + 1
  - o Temporary = Temporary + C\_HIGH
    - If (Cflag==1) Carry= Carry + 1
  - $\circ$  **RES\_2** = Temporary + D\_LOW
    - If (Cflag==1) Carry= Carry + 1
- $RES_3 = D_HIGH + Carry$

Οι ρουτίνες που χρησιμοποιήθηκαν φαίνονται παρακάτω:

READ_8HEX_DIG	Χρησιμοποιείται για ανάγνωση ενός 8ψήφιου (το πολύ) 16αδικού αριθμού. Με το <b>ENTER</b> τερματίζεται η είσοδος. Με το '/' τερματίζεται το πρόγραμμα. Επιστρέφει τον 32bito αριθμό στους καταχωρητές DX-BX.
ABCD_MAKE	Δημιουργεί τους <b>A, B, C, D</b> όπως αυτόι προαναφέρθηκαν, κάνοντας τους ανάλογους πολλαπλασιασμούς. Αποθηκεύονται στις αντίστοιχες μεταβλητές (*_LOW, *_HIGH)
CALCULATION	Πραγματοποιεί τις απαιτούμενες προσθέσεις με στόχο την δημιουργία του 64bitou <b>RESULT.</b>
PRINT_HEX	Τυπώνει σε δεκαεξαδική μορφή τον αριθμό που βρίσκεται στον καταχωρητή DL (00 - 0F)
PRINT_16BIT	Τυπώνει σε δεκαεξαδική μορφή τον 16bit αριθμό που βρίσκεται στον καταχωρητή ΑΧ. Χρησιμοποιεί την PRINT_HEX
PRINT_RESULT	Τυπώνει σε δεκαεξαδική μορφή τον 64bit αριθμό που βρίσκεται στην μνήμη (RES_3 - RES 0). Χρησιμοποιεί την PRINT 16BIT

Ο κώδικας φαίνεται παρακάτω.

#### **INCLUDE MACROS.TXT**

```
STACK SEG SEGMENT STACK
 DW 128 DUP(?)
ENDS
DATA_SEG SEGMENT
 LINE DB 0AH,0DH,"$"
 FIRST_NUM DB "FIRST NUMBER:$"
       SECOND_NUM DB "SECOND NUMBER:$"
       RES NUM DB "RESULT:$"
 QUIT_QUEST DB "PRESS ANY KEY TO RESTART OR '/' TO EXIT...$"
       X0 DW?
       X1 DW?
       Y0 DW?
       Y1 DW?
       A HIGH DW?
       A_LOW DW?
       B HIGH DW?
       B_LOW DW?
       C_HIGH DW?
       C LOW DW?
       D_HIGH DW?
       D_LOW DW?
       RES 0 DW?
       RES_1 DW?
       RES_2 DW?
       RES_3 DW?
ENDS
CODE SEG SEGMENT
 ASSUME CS:CODE_SEG,SS:STACK_SEG,DS:DATA_SEG,ES:DATA_SEG
MAIN PROC FAR
 ;SET SEGMENT REGISTERS
 MOV AX, DATA_SEG
 MOV DS,AX
 MOV ES, AX
;=-=---CODE-----
START:
;[/reading]
 PRINT_STRING FIRST_NUM
       CALL READ_8HEX_DIG
       MOV X0,BX
       MOV X1,DX
 PRINT_STRING SECOND_NUM
       CALL READ 8HEX DIG
       MOV YO,BX
       MOV Y1,DX
;[/reading ends]
       CALL ABCD MAKE
       CALL CALCULATION
       PRINT_STRING RES_NUM
       CALL PRINT_RESULT
       PRINT_STRING LINE
       PRINT_STRING QUIT_QUEST
       READ
       CMP AL,'/'
```

```
JE EXODOS
       PRINT STRING LINE
       JMP START
EXODOS:
 EXIT
MAIN ENDP
;-----ROUTINES-----
;[/routine = READ_8HEX_DIG]
READ_8HEX_DIG PROC NEAR
;Messes with AX,BX,CX,DX,SI returns 32bit input at DX-BX
       MOV CX,8
       MOV BX,0
       MOV DX,0
INPUT_NUM:
       PUSH DX
IGNORE READ:
       READ
       CMP AL,'/'
       JE EXODOS
       CMP AL,0DH
                               ;ODH = ENTER (ASCII)
       JE FORCED_END
                       ;Forced end, before 8hex digits have been inputed
       CMP AL,30H
       JL IGNORE_READ
       CMP AL,39H
       JG HEX CHECK
       PRINT AL
       SUB AL,30H
       JMP READ OUT
HEX_CHECK:
       CMP AL,'A'
       JL IGNORE_READ
       CMP AL,'F'
       JG IGNORE_READ
       PRINT AL
       SUB AL,37H
READ_OUT:
                               ;Here AL <- 0000 (0000 to 1111)
       POP DX
       ;[/code] Shifts left DX-BX, which handled like one 32bit register
       ROL BX,4
       SHL DX,4
       MOV SI,000FH
       AND SI, BX
       OR DX,SI
       AND BX,0FFF0H
       OR BL,AL
       ;[/code ends]
       LOOP INPUT_NUM
INPUT_ENDED:
       PRINT_STRING LINE
       RET
FORCED_END:
       POP DX
       JMP INPUT_ENDED
READ_8HEX_DIG ENDP
;[/routine ends]
```

```
;[/routine = ABCD_MAKE]
ABCD_MAKE PROC NEAR
;MAKING A(32bits) = A_HIGH \mid A_LOW : X0*Y0
       MOV AX,X0
       MUL Y0
       MOV A_HIGH,DX
       MOV A_LOW,AX
;MAKING B(32bits) = B_HIGH \mid B_LOW : X0*Y1
       MOV AX,X0
       MUL Y1
       MOV B_HIGH,DX
       MOV B LOW, AX
;MAKING C(32bits) = C_HIGH \mid C_LOW : X1*Y0
       MOV AX,X1
       MUL Y0
       MOV C_HIGH,DX
       MOV C_LOW,AX
;MAKING D(32bits) = C_HIGH \mid C_LOW : X1*Y1
       MOV AX,X1
       MUL Y1
       MOV D_HIGH,DX
       MOV D_LOW,AX
       RET
ABCD MAKE ENDP
;[/routine ends]
;[/routine = CALCULATION]
CALCULATION PROC NEAR
MOV CX,0
                             ;CX = CARRY
;MAKING RES 0
       MOV AX, A_LOW
       MOV RES_0,AX
;MAKING RES 1
       MOV AX,A_HIGH
       ADD AX,B LOW
       JNC NEXT00
       INC CX
                             ;If C=1 must increase CARRY
NEXT00:
       ADD AX,C_LOW
                      ;AX \leftarrow A_HIGH + B_LOW + C_LOW
       JNC NEXT01
       INC CX
NEXT01:
       MOV RES 1,AX
;MAKING RES_2
       MOV AX,B_HIGH
       ADD AX,CX
       JNC NEXT02
       MOV CX,1
                             ;Making CARRY=1
       JMP NEXT03
NEXT02:
       MOV CX,0
NEXT03:
       ADD AX,C_HIGH
```

```
JNC NEXT04
        INC CX
NEXT04:
                         ;AX \leftarrow CARRY + B\_HIGH + C\_HIGH + D\_LOW
        ADD AX,D LOW
        JNC NEXT05
        INC CX
NEXT05:
        MOV RES_2,AX
;MAKING RES_3
        MOV AX,D_HIGH
        ADD AX,CX
                                 ;Trust math, that tell us there will not be any carry
        MOV RES_3,AX
        RET
CALCULATION ENDP
;[/routine ends]
;[/routine = PRINT HEX]
PRINT_HEX PROC NEAR
;PRINTS DL(hex) <- 0 0 0 0 (0000 - FFFF)
        CMP DL,9
        JG ADDR_42
        ADD DL,30H
        JMP ADDR_R6
ADDR_42:
        ADD DL,37H
ADDR_R6:
        PRINT DL
        RET
PRINT_HEX ENDP
;[/routine ends]
;[/routine = PRINT_16BIT]
PRINT 16BIT PROC NEAR
;Having at AX <- LMNO H, and want to print L,M,N and O
        MOV CX,4
                         ;repeat 4 times (4hex digits exist within a 16bit reg)
        CMP SI,0
        JNE PRINT_16_2
PRINT_16:
                         ;If flag is still 0 (nothing non-zero have printed yet) we are here
        ROL AX,4
        MOV DL,0FH
        AND DL,AL
        CMP DL,0
        JNE GO ON
        LOOP PRINT_16
        JMP END_PRINT_16BIT
GO ON:
        MOV SI,1
                                          ;Flag that from now on must print zeros
        CALL PRINT_HEX
        JMP LOOP_LOOP
                            ; We don't use DEC CX, because if this has result CX = 0,
                  ;LOOP PRINT_16_2 will make CX = FFFF H and keep looping!
PRINT_16_2:
        ROL AX,4
        MOV DL,0FH
        AND DL,AL
```

```
CALL PRINT_HEX
LOOP LOOP:
         LOOP PRINT_16_2
END PRINT 16BIT:
         RET
PRINT 16BIT ENDP
;[/routine ends]
;[/routine = PRINT_RESULT]
PRINT_RESULT PROC NEAR
         MOV SI,0
                                    ;Flag for first non-zero number to print
         MOV AX,RES 3
         CALL PRINT_16BIT
         MOV AX,RES 2
         CALL PRINT 16BIT
         MOV AX,RES_1
         CALL PRINT_16BIT
         MOV AX,RES_0
         CALL PRINT_16BIT
         CMP SI,0
                             ;If the result is just zero, print it!
         JNE PRINT_RESULT_END
         PRINT 30H
PRINT RESULT END:
         RET
PRINT_RESULT ENDP
CODE SEG ENDS
END MAIN
```

Τέλος αξίζει να αναφερθεί πως θα μπορούσαμε να παραλείψουμε τις ενδιάμεσες αποθηκεύσεις στην μνήμη, δηλαδή στις μεταβλητές **A,B,C,D** (\_LOW, \_HIGH). Περιγράφουμε την διαδικασία και τους καταχωρητές που χρησιμοποιύμε στο επόμενο σχήμα. Θεωρούμε ότι πριν από κάθε πολλαπλασιασμό φέρνουμε τα Xi, Yi που χρειάζονται από την μνήμη. Βέβαια τοιουτοτρόπως η λειτουργία του προγράμματος γίνεται λιγότερο σαφής στο ενδιάμεσο στάδιο των υπολογισμών και ο κώδικας που θα προέκυπτε λιγότερο ευανάγνωστος.

