

NM-2023-27: Gauging performed during receipt into T-301

Incident / Near-Miss Report: NM-2023-27 Category: near_miss_procedural

Date: 2023-11-08 Area: Area 3 Equipment: T-301

Title: Gauging performed during receipt into T-301

NARRATIVE:

Operator opened gauge hatch while tank was receiving HSD, contrary to SOP-TK-014 static precautions. Stopped by supervisor.

ROOT CAUSE: Task pressure; SOP awareness gap.

PRECURSOR CONDITIONS: tank receiving; manual gauging

CORRECTIVE ACTIONS: Toolbox talk; interlock signage at gauge platform.

Reported to: M. Pillai (Safety Officer)