

INSPECTION REPORT INSP-STR101-2021-08-02

Inspection Report: INSP-STR101-2021-08-02

Equipment / Location: STR-101 Date: 2021-08-02

Method: dP gauge reading Result: ALERT

DETAILS:

STR-101 differential pressure recorded 0.85 bar (normal < 0.3, clean ~0.1). Basket blinding consistent with monsoon CW turbidity from CT-101 basin. Cleaning recommended within 48 h.

Inspector: N. Kaur (Inspection Engineer)