

WORK ORDER WO-2021-0843

Work Order No: WO-2021-0843 Type: CM Priority: P3

Equipment: P-101 Date completed: 2021-08-05

Title: P-101 seal failure - replace cartridge seal

FINDINGS / WORK PERFORMED:

Second wet-season seal loss. Face pattern identical to 2019 event: thermal crazing + abrasive scoring. STR-101 differential pressure logged 0.9 bar the same week (normal < 0.3).

Recommended monsoon strainer cleaning frequency be doubled - NOT implemented at the time.

Parts used: MS-40D cartridge seal x1

Labor hours: 12 Equipment downtime: 8 h

Raised by: A. Deshpande (Maintenance Planner)

Closed by: R. K. Sharma (Senior Reliability Engineer (retiring Dec 2026))

Reference drawing: D-CW-104 rev 3