

WORK ORDER WO-2023-0921

Work Order No: WO-2023-0921 Type: CM Priority: P3

Equipment: P-107 Date completed: 2023-09-14

Title: P-107 effluent pump seal leak

FINDINGS / WORK PERFORMED:

MS-40D seal leak on effluent service. High solids in TK-401 equalization tank during monsoon; same seal model as CW pumps. Abrasive wear pattern.

Parts used: MS-40D cartridge seal x1

Labor hours: 9 Equipment downtime: 5 h

Raised by: A. Deshpande (Maintenance Planner)

Closed by: S. Venkatesan (Shift Supervisor)

Reference drawing: D-ET-401 rev 1