

WORK ORDER WO-2024-0733

Work Order No: WO-2024-0733 Type: CM Priority: P3

Equipment: P-103 Date completed: 2024-07-30

Title: P-103 seal replacement (second wet-season failure)

FINDINGS / WORK PERFORMED:

Second monsoon failure on P-103. Seal face condition matches P-101 pattern. Recommend including P-103 in monsoon-mode flush verification round (currently only P-101/P-102 covered by SOP-CW-012).

Parts used: MS-40D cartridge seal x1

Labor hours: 11 Equipment downtime: 7 h

Raised by: A. Deshpande (Maintenance Planner)

Closed by: R. K. Sharma (Senior Reliability Engineer (retiring Dec 2026))

Reference drawing: D-CW-104 rev 3