

WORK ORDER WO-2025-4620

Work Order No: WO-2025-4620 Type: breakdown Priority: P1

Equipment: P-101 Date completed: 2025-09-02

Title: P-101 high temperature trip (repeat) - TI-1103

FINDINGS / WORK PERFORMED:

Second high-temp trip of the season, same signature as WO-2025-4471. E-201 fouling confirmed by dP survey; chemical clean completed. Root cause: fouled cooler. Action: E-201 monsoon backflush schedule added to PM plan for 2026.

Parts used: cleaning chemicals

Labor hours: 8 Equipment downtime: 5 h

Raised by: S. Venkatesan (Shift Supervisor)

Closed by: R. K. Sharma (Senior Reliability Engineer (retiring Dec 2026))

Reference drawing: D-CW-104 rev 3