

## Legend

**Location Numbers** 

Positive Asbestos Bulk Sample Location (16313-xx)

Negative Asbestos Bulk Sample Location (16313-xx)

Lead Bulk Sample Location (16313-Pb-xx)



Asbestos-Containing Vinyl Floor Tiles & Mastic (Non-Friable)

Asbestos-Containing Texture Finish (Friable)



Asbestos-Containing Mastic (Non-Friable)

Area Not Investigated

Asbestos-containing vinyl floor tile mastic may be present in other location not identified on this drawing

All information relating to room size and location is approximate and for visual aid only. ECOH does not guarantee the drawing to be complete, absolute, accurate or current. The drawing should not be used by any party in lieu of obtaining architectural drawings.

## Figure 15

Fifteenth Floor Plan

255 Riverside Drive, Windsor, Ontario

**Designated Substances Survey** 

Windsor Essex Community Housing Corporation

DATE: March 2016 SCALE: Not to Scale снк ву: МВ FIG1-22 P16313 DSUB Bsmt-21

