Building Summary Report

Client Name: Windsor -ESSEX Community Housing Corporation (CHC)

Building Address: 1323 Tilston Ave

Development: Bridgeview I

District: 2

			AATT DIAL				TOTAL		HAZAROUS CONTENT			FCTIMATED
SYSTEM	MATERIAL NAME	MATERIAL IDENTIFICATION	MATERIAL DESCRIPTION	LOCATIONS	FRIABILITY	ACCESSIBILITY	TOTAL QUANTITY	UNITS	RESULTS	HAZARD	PRIORITY	ESTIMATED COST
Floor	Vinyl Floor Tiles	VFT1	12"x12" Beige with black veins	9127502 ,9127503 ,9127504	N	А	200	SF	Chrysotile 2%	Confirmed Asbestos	Priority 3	
Floor	Vinyl Floor Tiles	VFT3	9"x 9" Black with light brown streak	9130601	N	А	80	SF	Chrysotile 2%	Confirmed Asbestos	Priority 3	
Ducts	Heat Shield	N/A	Heat Shield	9133901 ,9130601 ,9118101 ,9230001 ,9127701 ,997201 ,9101401	Y	С	24	SF	Chrysotile 60%	Confirmed Asbestos	Priority 1	