500 MPa Steel (NZS3101:2006) - Stress-Strain Profile 400 200 0 -200-400-0.100 -0.075 -0.050 -0.0250.000 0.025 0.050 0.075 0.100 Strain