

Do not populate red components.

Populate blue componenents after SMT assembly.