

Do not populate red components. Populate blue components after SMT assembly.