



RED BANNER ALERT



mainroads
WESTERN AUSTRALIA

SHW Serious Incident (SI) – Preliminary Notice

Date of Incident:	7 th July 2023	Time of Incident:	9.30am
Directorate / Region:	MET – Metro	Main Roads or Contractor:	Contractor
EQSafe Event Type:	Injury/ Illness	EQSafe Incident Number:	32512
Actual Consequence:	Moderate	Potential Consequence:	Catastrophic

Incident Short Description:	Member of Public collides with stationary Traffic Control utility, injuring Traffic Controller
------------------------------------	--

What Happened:

At approximately 9.30am on Friday 7th July, a Member of Public (MoP) was travelling in a north westerly direction towards the traffic signalled intersection. An electrical Contractor was at this location performing CCTV camera maintenance and were utilising the services of a sub-contractor to provide Traffic Management (TM).

For reasons unknown, the MoP has left the road and travelled approximately 120m through the verge, missing large trees and an electrical pillar, and has collided with the stationary and unoccupied TM utility situated approximately 10-12m off the roadway.

When the MoP vehicle has collided with the TM utility, the force of the collision has caused the utility to strike a Traffic Controller (TC) who was standing outside of the cab and has forced him to the ground. No other persons were injured.

The on-site Foreman has contacted emergency services, and their immediate Supervisor. Works were ceased.

WA Police and St John Ambulance have attended the scene, where the TC was attended to immediately and transferred to hospital.

TC was released from hospital at approximately 1.30pm on the same day and did not require treatment.

A formal ICAM investigation has commenced. Once completed, the lessons learnt will be communicated/shared through a final Grey Banner alert as soon as practicable.



Images showing impact Traffic Management Utility



Images showing impact Member of Public light vehicle



This serious potential incident aligns with the Main Roads Critical Risk profile
Relating to **Interaction with Live Traffic**.

Immediate Actions/ Notes:

Please note that these are generic actions for all to consider in relation to this risk (and is not reflective of this specific incident):

- *Ensure risk assessments have been conducted to assess each working environment.*
- *Ensure all workers are aware of site layout and pre-start covers appropriate escape routes.*
- *Ensure processes in place to look out for, and warn workers of, errant vehicles*

Distribution of Notice:

Main Roads Personnel and Contracting Organisations

