

RED BANNER ALERT**Serious Incident – Preliminary Notice****CRITICAL RISK: Dropped Objects**

Date of Incident	13/08/2026	Time of Incident	12:12 PM
Directorate / Region	OMTID	Main Roads or Contractor	Contractor
isafe Event Type	Damage / Loss	isafe Incident Number	INC-000057
Actual Consequence	Minor	Potential Consequence	Major
Reportable to WorkSafe	Yes	Type of Notifiable Incident	Dangerous incident - the fall or release from a height of any plant, substance or thing

Incident Short Description	Auxiliary hook fell approximately 14m into an established exclusion zone following auxiliary line failure during piling operations.
-----------------------------------	---

What Happened

During piling operations, the piling contractor was installing the final segment of a precast concrete pile. The piling rig auxiliary line failed during pile driving after tension increased on the line, causing the auxiliary hook to fall approximately 14 metres. The hook landed within the established hard-barricaded exclusion zone, with no personnel present in the drop zone and no injuries, asset damage or environmental impacts reported.

*Image 1: Pile**Image 2: Dropped auxiliary hook*

Work ceased, and the area was secured. The client and regulator were notified, witness statements obtained, for-cause D&A testing completed, and a formal ICAM investigation commenced. Designers were consulted regarding pile stability.

Distribution of Notice	Main Roads Personnel and Contracting Organisations
-------------------------------	--