



RED BANNER ALERT

mainroads
WESTERN AUSTRALIA

SHW Serious Incident (SI) – Preliminary Notice

Date of Incident	14/05/2026	Time of Incident	1835 Hrs
Directorate / Region	Metropolitan Region\Electrical Asset Management	Main Roads or Contractor	Contractor
Event Type	Injury	isafe Incident Number	INC-0150
Actual Consequence	Major	Potential Consequence	Major

Incident Short Description	Electrician contacted electricity during termination of a third-party damaged traffic signal Lantern
-----------------------------------	--

What Happened

Electrician 1 (IP) and electrician 2 were assigned a lantern fault located at Mitchell Fwy & Hutton Street in Osborne Park. The task was to replace traffic signal pole that had been damaged by member of the public's vehicle, creating an emergency hazardous situation.

The damaged pole was removed and the ground was made ready for installation of the new pole. The new pole cables and pole top were attached by electrician 1 (IP) whilst the pole was on the ground. After standing the pole, the lanterns were installed. Whilst fitting off the ring main cable at the pole, electrician 1 (IP) noticed that the plastic cover (boot) for the neutral wire was too far down and likely to have prevented the cable from being plugged back in.

Electrician 1 (IP) tried to slide the plastic cover (boot) back carefully without touching anything but came into contact with the metal terminal when applying force to the plastic protector resulting in a mild electric shock to the left hand.

Immediately after the incident:

- Wellbeing check was completed with the involved person by the other employee on site
- Supervisor was notified of event by electrician 1 (IP)
- Supervisor notified Project Director and TIS & Road Operations SHEQ Manager
- MRWA Superintendent notified of event
- The IP attended Osborne Park Urgent Care Clinic where they were medically assessed and released without injury

WorkSafe has been notified.

A formal ICAM investigation has commenced. Once completed, the lessons learnt will be communicated/shared through a final Grey Banner Alert as soon as practicable.



This serious potential incident aligns with the Main Roads Critical Risk profile relating to **Electric Shock & Arc Flash**

Distribution of Notice

Main Roads Personnel and Contracting Organisations