

Item (Generic / Site Specific)			Risk Event	Consequence	Pre-treatment Risk			Treatment	Residual Risk		
					L	C	RR		L	C	RR
3.2.	16	4 G	Insufficient room on verge or within emergency lane for advanced warning vehicle due to existing barrier or other roadside furniture causing vehicles to be unaware of mobile convoy resulting in serious injuries or fatality.	Serious injury or fatality.	C	4	H12	0922-01531-MS2-007 and MS3-007 to be utilised where there is insufficient room for advanced warning vehicle. Where the advanced warning vehicle must enter the live lane on high speed/volume roads it must be a TMA or be shadowed by a TMA.	D	4	M8
3.2.	16	5 G	Existing posted speed signs not covered during mobile works convoy causing an increase of speed through the worksite resulting in serious injury or fatality.	Serious injury or fatality.	C	4	H12	Mobile works convoy will be constantly moving and may only be in the vicinity of an existing posted speed sign for a short duration. Covering the existing posted speed sign may expose Traffic Management Personnel to unnecessary risk. Vehicles within the mobile convoy must display the proposed temporary speed zones at all times.	D	4	M8
3.2.	16	6 G	Insufficient sight distance to start of convoy causing road users inadequate time to perceive and react to a hazardous situation resulting in serious injury or fatality.	Serious injury or fatality.	C	4	H12	Sight distance to the start of the convoy is best when as long as practicable, but is often restricted by numerous site constraints. Sight distance requirements, where possible should meet the distance requirements for vehicle mounted warning devices of: - 150m for traffic speed 60km/h or less - 250m for traffic speeds greater than 60km/h.	D	4	M8
3.2	17	7 G	Traffic may approach at a higher rate of speed during 80km/h scenarios due to the lack of advanced warning buffer	Serious injury or fatality.	C	4	H12	Advanced warning devices are to be used in all scenarios where the speed is reduced below 80km/h, however a speed buffer cannot be provided where the speed is 80km/h past the works as a temporary speed zone above 80km/h cannot be provided as per MRWA CoP	D	4	M8
3.2.	17	Turning Restriction Impacts									
3.2	17	1 G	Traffic distribution from proposed turning restriction causing an increase of traffic flow in adjacent local network resulting in adverse public reaction.	Adverse public reaction.	B	3	H12	Notification is required to affected roads and local residents prior to works commencement. Details of potential detours and impacts on road network are required. Pre-communication may include; VMS boards, letter drops and radio advertising. Significant congestion and delays will require the removal of proposed temporary traffic management until the congestion has cleared.	C	3	M9