

**RED BANNER ALERT****mainroads**
WESTERN AUSTRALIA**SHW Serious Incident (SI) – Preliminary Notice**

Date of Incident	2 July 2024	Time of Incident	3:50pm
Directorate / Region	RMO – Pilbara	Main Roads or Contractor	Main Roads
EQSafe Event Type	Near Miss	EQSafe Incident Number	42098
Actual Consequence	Insignificant	Potential Consequence	Major

Incident Short Description	Learner driver overtaking causes maintenance truck to veer from road.
-----------------------------------	---

What Happened

At approximately 3:50pm, a Main Roads maintenance truck was travelling on a highway returning to the depot at the end of shift. A road train was travelling in front of the maintenance truck and two Member of Public (MoP) light vehicles (LV) were travelling behind the maintenance truck.

The rear MoP LV (learner driver) has proceeded to overtake the LV and maintenance truck, passing the maintenance truck and beginning to overtake the road train in front. The MoP has then realised that there was oncoming traffic, braked and veered back into the lane between the road train and maintenance truck.

To avoid collision with the MoP LV, the maintenance truck has had to veer off the road onto the shoulder at a speed of 100km/hr. The maintenance truck was able to remain in control and veer back onto the road, and there was no damage or injuries reported.

A formal ICAM investigation has commenced. Once completed, the lessons learnt will be communicated/shared through a final Grey Banner Alert as soon as practicable.



This serious potential incident aligns with the Main Roads Critical Risk profile relating to
Vehicles & Driving

Distribution of Notice	Main Roads Personnel and Contracting Organisations
-------------------------------	--