



RED BANNER ALERT




SHW Serious Incident (SI) – Preliminary Notice

Date of Incident	12th February 2025	Time of Incident	3:00PM
Directorate / Region	RMO - Goldfields Esperance	Main Roads or Contractor	Contractor
EQSafe Event Type	Near Miss	EQSafe Incident Number	48096
Actual Consequence	Insignificant	Potential Consequence	Major

Incident Short Description	Worker enters live lane to place traffic control signage
-----------------------------------	--

What Happened
At approximately 3:00pm during a site visit by contractor senior management, it was observed on three (3) occasions where TC workers crossed the live lane on foot to change signs. On each occasion there was no active spotter. Additionally, a TC operator was observed pulling signs from the back of a ute while standing on the fog line. Supervisors were notified of the near miss. A meeting occurred with all traffic control team leaders and contractor management team to address the issues identified. A formal ICAM investigation has commenced. Once completed, the lessons learnt will be communicated/shared through a final Grey Banner Alert as soon as practicable.  This serious potential incident aligns with the Main Roads Critical Risk profile relating to Interaction With Live Traffic

Distribution of Notice	Main Roads Personnel and Contracting Organisations
-------------------------------	--