

RED BANNER ALERT**Serious Incident – Preliminary Notice****CRITICAL RISK: Vehicles and Driving**

Date of Incident	1 st September 2026	Time of Incident	13:30
Directorate / Region	OMTID	Main Roads or Contractor	Contractor
isafe Event Type	Near Miss	isafe Incident Number	INC-0000629
Actual Consequence	NA	Potential Consequence	Catastrophic
Reportable to WorkSafe	Yes	Type of Notifiable Incident	

Incident Short Description	Vehicle Enters Active Rail Crossing
-----------------------------------	-------------------------------------

What Happened

At approximately 13:30, two project personnel travelling between the Bishop Road and Orton Road compounds entered the Hopkinson Road rail crossing while the red flashing warning lights were active. As the vehicle traversed the crossing, an approaching westbound train sounded its horn to alert the occupants. The vehicle cleared the crossing safely with no collision, injuries, damage, or environmental impacts. The event was immediately reported to site supervision.

An investigation has immediately commenced into the event. Witness statements were obtained from the personnel involved and drug and alcohol testing was undertaken. ARC Infrastructure advised that ONRSR will be notified of the event for information purposes only.



Figure 1: Hopkinson Road rail crossing showing the location of the rail crossing event

A formal ICAM investigation has commenced. Once completed, the lessons learnt will be communicated through a Grey Banner Alert as soon as practicable.

Distribution of Notice

Main Roads Personnel and Contracting Organisations