

Figure 5.9.4(b) – Closing a shoulder at a 45 degree angle where a taper is required




Figure 5.9.4(c) – Closing a shoulder at a 45 degree angle where a taper is required and a lead-in is provided




Figure 5.9.4(d) – Closing a shoulder with a square treatment where a taper is required

