

GREY BANNER ALERT



Serious Incident – Final Notice

CRITICAL RISK: Vehicles and Driving

Date of Incident	14/04/2026	Time of Incident	12:20 PM
Directorate / Region	RMO MWG	Main Roads or Contractor	Contractor
isafe Event Type	Near Miss	isafe Incident Number	INC-0000054
Actual Consequence	Insignificant	Potential Consequence	Major
Reportable to WorkSafe	No	Type of Notifiable Incident	N/A


Incident Short Description	Near Miss During Overtaking Manoeuvre
-----------------------------------	---------------------------------------

Executive Summary

On Tuesday 14 April 2026 at approximately 12:20 PM, an empty 8-wheel tipper (Truck 1) travelling northbound attempted an overtaking manoeuvre in a section of road with only around 500 metres of broken white line marking. At the same time, a loaded double side tipper (Truck 2) was travelling southbound in a 110 km/h speed zone at approximately 90 km/h, transporting gravel material. Both heavy vehicles were associated with the project works.

Truck 2 was clearly visible to Truck 1 when Truck 1 commenced the overtaking manoeuvre. After overtaking two vehicles, Truck 1 was unable to safely complete the manoeuvre and was forced to return to the northbound lane. Truck 1 narrowly merged back into the traffic stream approximately 80 metres from the oncoming Truck 2. One of the northbound light vehicles had reduced its speed to create a gap for Truck 1 to move into. At the same time, the operator of Truck 2 had moved the left wheels onto the gravel shoulder and slowed as much as possible to increase separation.

Approximately one kilometre further north, Truck 1 again attempted an overtaking manoeuvre, this time passing another heavy vehicle within a short overtaking section on the approach to a crest, where sight distance was limited.



Northbound View at First Overtaking Location



Northbound View at Second Overtaking Location

Contributing Factors

- IP conducted an overtaking manoeuvre when it was not safe to do so, contrary to the project SWMS and the requirements of Regulation 121 of the Road Traffic Code 2000 (WA). (Regulation 121 of the Road Traffic Code 2000 (WA) requires overtaking to be completed safely and only when sufficient clear distance is available.)
- IP was attempting to progress ahead of traffic and did not adequately consider the risks associated with overtaking.
- The driver had previously been involved in a breach and other performance concerns and remained under performance monitoring at the time of the incident.

Corrective Actions

- Continued communication of Critical Risk - Vehicles and Driving
- Worker to be stood down from duties on the project and returned to the contractor (the worker's employer) for further management, discipline and development.

Distribution of Notice

Main Roads Personnel and Contracting Organisations