



RED BANNER ALERT

mainroads
WESTERN AUSTRALIA

SHW Serious Incident (SI) – Preliminary Notice

Date of Incident	12 October 2023	Time of Incident	1230
Directorate / Region	IDD	Main Roads or Contractor	Contractor
EQSafe Event Type	Near Miss – Procedural Breach	EQSafe Incident Number	34442
Actual Consequence	Insignificant	Potential Consequence	Moderate

Incident Short Description	Tree Lopper worked outside approved Traffic Guidance Scheme (TGS)
-----------------------------------	---

What Happened

A Tree Lopper Contractor was required to complete some clearing on site.

Proper to the works being conducted, the worker was clearly instructed, and advised on where they were required to complete the task, and which gate they should use to enter the work location.

During the task, the worker needed to move the chipper and mulch truck, to allow for safe removal of a tree (loaded to one side). They placed the truck and chipper on the opposite side of the clearing area and the already set up TGS.

As a result, the worker required, a new area to be delineated and proceeding to exit, the designated work zone, and placed traffic cones, along the kerb for approximately 15m outside the approved TGS.



Tree Lopper working in the work zone.

A formal ICAM investigation has commenced. Once completed, the lessons learnt will be communicated/shared through a final Grey Banner Alert as soon as practicable.



This serious potential incident aligns with the Main Roads Critical Risk profile relating to **Interaction with Live Traffic**

Distribution of Notice

Main Roads Personnel and Contracting Organisations