



RED BANNER ALERT

mainroads
WESTERN AUSTRALIA

SHW Serious Incident (SI) – Preliminary Notice

Date of Incident	7 November 2023	Time of Incident	1100
Directorate / Region	MWG RMO	Main Roads or Contractor	Main Roads
EQSafe Event Type	Near Miss / Hit	EQSafe Incident Number	35210
Actual Consequence	Minor	Potential Consequence	Major


Incident Short Description	Three-point turn conducted across carriageway in maintenance truck
-----------------------------------	--

What Happened

At approximately 1100 on 7 November 2023, the driver of a routine maintenance truck was heading east along Geraldton-Mt Magnet Road.

As works on a defect were required to be undertaken on the opposite traffic lane, the driver pulled over to the left side of the road with the intention to conduct a U-Turn across the carriageway.

The driver was unable to complete the turn in one motion and had to await a westbound passing truck (double – Cat 5) that had to navigate across the double white lines into the opposite lane before the maintenance truck could pull back again and complete a three-point turn.



Marks on the shoulder shows where the maintenance truck's front wheels were after the first turn across the carriageway, and the centre line where the end of the truck was situated as the Cat- 5 double was passing.



Eastbound line of sight



Westbound line of sight

A formal ICAM investigation has commenced. Once completed, the lessons learnt will be communicated/shared through a final Grey Banner Alert as soon as practicable.



This serious potential incident aligns with the Main Roads Critical Risk profile relating to
Vehicles and Driving

Distribution of Notice

Main Roads Personnel and Contracting Organisations