



RED BANNER ALERT



SHW Serious Incident (SI) – Preliminary Notice

Date of Incident	13 November 2023	Time of Incident	1130
Directorate / Region	Goldfields Esperance	Main Roads or Contractor	Employee
EQSafe Event Type	SHW Incident - Injury	EQSafe Incident Number	35216
Actual Consequence	Moderate	Potential Consequence	Major

Incident Short Description	MOP collided with Main Roads Employee after veering into oncoming lane
-----------------------------------	--

What Happened

On 13 November at 1130, a Maintenance Supervisor was travelling westbound on the Highway trailing a contractor's water truck when a member of public (MOP) travelling in the opposite direction (eastbound) has drifted across to the RHS of the road (oncoming traffic lane) and struck the front RHS of the Maintenance Supervisor's light vehicle. The Maintenance Supervisor's light vehicle remained on the RHS carriageway, whilst the MOP's vehicle has slewed back to the LHS and come to rest in the table drain on the LHS of the road.

The Maintenance Supervisor and Contractor were between pavement repair sections when the incident occurred with the MOP.

The Main Roads LV currently leased sustained damaged to the driver's side front panels and tyres.

The Supervisor and MOP were transported to the hospital.



Damage to Main Roads Vehicle

A formal ICAM investigation has commenced. Once completed, the lessons learnt will be communicated/shared through a final Grey Banner Alert as soon as practicable.



This serious potential incident aligns with the Main Roads Critical Risk profile relating to **Vehicles and Driving**

Distribution of Notice	Main Roads Personnel and Contracting Organisations
-----------------------------------	--