



RED BANNER ALERT

mainroads
WESTERN AUSTRALIA

SHW Serious Incident (SI) – Preliminary Notice

Date of Incident	16 January 2024	Time of Incident	1230
Directorate / Region	IDD	Main Roads or Contractor	Subcontractor
EQSafe Event Type	Near Miss – Damage	EQSafe Incident Number	37056
Actual Consequence	Insignificant	Potential Consequence	Major

Incident Short Description	Uncontrolled movement of contractor 6T tipper truck within project work area.
-----------------------------------	---

What Happened

On 16 January, a 6T Tipper Truck had been parked up adjacent to a stockpile and was being loaded by a posi-track with rock pitching material. At 1230 after loading approx. four (4) bucket loads of material the truck began moving uncontrolled, rolling down an access track approx. 60 metres. The truck came to rest in a parallel sand embankment.

There operator was not in the vehicle when the incident occurred. No personnel were in the vicinity of the incident work area when the event occurred.

Once the truck stopped, all works in the area was stopped and the site was secured.



Truck in its final position post incident. Barricading was put in place post incident to preserve the scene.



Alternative view of the Truck in its final position post incident.



Picture of the access track and the truck in its final position post incident.

A formal ICAM investigation has commenced. Once completed, the lessons learnt will be communicated/shared through a final Grey Banner Alert as soon as practicable.



This serious potential incident aligns with the Main Roads Critical Risk profile relating to
Vehicles and Driving

Distribution of Notice	Main Roads Personnel and Contracting Organisations
-------------------------------	--