RED BANNER ALERT

mainroads WESTERN AUSTRALIA

SHW Serious Incident (SI) – Preliminary Notice

Date of Incident	11 April 2026	**Time of Incident**	6:15 AM
Directorate / Region	RMO – Mid West – Gascoyne Region	**Main Roads or Contractor**	Contractor
EQSafe Event Type	Injury	**EQSafe Incident Number**	57872
Actual Consequence	Moderate	**Potential Consequence**	Moderate

Incident Short Description	Traffic Controller sustains shoulder injury slipping on roadside batter

What Happened

On Saturday, 11 April 2026, at 6:15 AM whilst setting up traffic management signage for a road widening project, a Traffic Controller (TC) exited their vehicle on the passenger side. The TC's feet slipped out from underneath them as they stood up on the soft batter at the shoulder of the road. In response to the slip, the TC grabbed the door with their right hand and reached up and behind with their left to grab the roll bar on the back of the Ute. They immediately felt pain in their left shoulder as they righted themself. The TC completed the site set up however was unable to continue works due to the pain and reported it to their crew leader.

First aid was administered, and the TC was taken to the emergency department for assessment. Initial x-rays did not show any damage to the shoulder bones however further assessment with an ultrasound is required. The TC was prescribed medication for pain and inflammation and deemed 'unfit for work' for 2 weeks, resulting in a Lost Time Injury (LTI).



Location of vehicle on road shoulder and reenactment photo taken at the same time of day, the following morning.

A formal ICAM investigation has commenced. Once completed, the lessons learnt will be communicated/shared through a final Grey Banner Alert as soon as practicable.

Distribution of Notice	Main Roads Personnel and Contracting Organisations