Aalmar
WORLDWIDE MARINE SURVEYS

MV ATLANTIC GREEN

OWNER'S REPORT
REF: UKS-26-02-0154

IMO: 9354404
INSPECTION DATE: 05.03.2026
LOCATION: ALGECIRAS
REPORT DATE: 07.03.2026
CLIENT: SILVER MARITIME C/O
Sinokor Merchant Marine Co Ltd

QUALITY**INDEPENDENCE**TRUST

Confidential Report © 2025. Aalmar Surveys Ltd.
All rights reserved.

SUMMARY OF REPORT SECTIONS

MAIN SECTION RATINGS *(click subject to jump to detailed information)*	VERY GOOD	GOOD	FAIR	POOR	UNSATIS-FACTORY
Section 1: Environmental, Social & Governance		✓			
Section 2: Accommodation		✓			
Section 3: Inspections and Survey Status	✓				
Section 4: Bridge Equipment		✓			
Section 5: Bridge & Deck Logbook		✓			
Section 6: Deck Safety & Security		✓			
Section 7: General Hull & Deck			✓		
Section 8: Cargo / Hatches / Holds				✓	
Section 9: Engine Room General		✓			
Section 10: Engine Control Room		✓			
Section 11: Engine Room Logbook & Oil Record Book		✓			
Section 12: Engine Room Equipment		✓			
Section 13: Engine Room Safety		✓			
Section 14: Steering Gear		✓			
Section 15: Emergency Generator Room		✓			
Section 16: Bunkers & Samples		✓			
Section 17: Ballast Tanks			✓		
Section 18: Lashing Gear Remaining Onboard		✓			
	GOOD				

TERMS & DEFINITIONS OF CONDITION

VERY GOOD	Unimpaired condition without significant wear, or deviation from original strength and operating efficiency. No maintenance or repair required.
GOOD	Unimpaired condition but may require some minor maintenance to bring to a good standard.
FAIR	Condition where wear and tear or other deficiencies of a minor nature, do not require correction or repair.
POOR	Condition in which the adequacy of strength and/or operational efficiency is marginally below acceptable limits, or is in doubt. Remedial action is required.
UNSATISFACTORY	Condition of inadequate strength or operational deficiency. Immediate extensive repair/renewal required, reinstating serviceability.

SURVEYOR'S SUMMARY

PRESENT AT SURVEY

Captain: Mr.Shanin Kyrylo

Chief Officer: Mr.Mandyev Vitaliy

Chief Engineer: Mr.Kulakov Victor

Aalmar Surveyor: Mr.Juan Antonio Notario

SUMMARY AND CONCLUSION

Comments:
We attended mv **"ATLANTIC GREEN"** to carry out a general condition survey, on behalf of the owners. The vessel was moored starboard alongside at APM TERMINAL, Algeciras (Spain).
This inspection took place on Thursday 05th March 2026 from 08:00 LT to 16:00LT.

During the inspection two terminal gantry crane was operating, discharging and loading containers from cargo holds, therefore ballasting in operation and only Fore Peak Tank available for inspection.

An introductory meeting was held in the cargo office with Master, C/O and C/E.

During our inspection we were assisted by:
Mr Shanin Kyrylo - Master
Mr Mandyev Vitaliy - Chief-Officer
Mr Chuyko Gennadiy- Second officer
Mr Kulakov Victor- Chief engineer
Mr Bredikhin Igor- Second engineer

The M/V **"ATLANTIC GREEN"** is a container ship 11,432 MT deadweight, with total 868 TEU capacity distributed in four cargo holds on deck. The vessel is equipped with two open-top cargo holds (N°3 & 4) and two holds (N°1 & 2) closed by hydraulic hinge type hatch covers.

"ATLANTIC GREEN", was built by J.J SIETAS KG Schiffswerft GmbH and Co of Hamburg, Germany, delivered on 11th August 2006 and built under DNV-GL (IACS) class. Vessel age is now 19 years.

She is under the register of Singapore flag and the class is BV; there is no Condition of class active at the date of the inspection. The RO and RSO is DNV.

The BV class notation is:
I✠HULL✠MACH Container ship (SOLAS II-2, Reg.19) Unrestricted navigation ✠ AUT-UMS, INWATERSURVEY

Her last class renewal survey was in November 2021, at Varna, Bulgaria and her last intermediate survey was on August 2024, next renewal survey is due in 5 months in August 2026, shipyard has not been arranged yet.

The following deficiencies/observations from previous inspection have been rectified:

- Cargo holds 2 & 3 bilge alarms sensor. – Has been repaired successfully.
- Electrical store cleanliness and organisation. - Organization has improved.
- Main Engine minor leaks.- No leakages observed now.
- Panama and rollers SWL.- Marks has been observed now.
- VDR Malfunction.- New VDR has been installed.
- Deck and forecastle floor rust spots.- New paint layer has been applied.
- Working hours records.- Same has been revised and found satisfactory now.
- Fuel Oil out of specification on tanks 3C, 2P & 1P. Contaminated fuel was de-bunkered last January.
- LSMGO Settling tank bacterial growth. Tank has been cleaned now.
- Some containers foundation has been now renewed. Job still in progress.
- No major/main maintenance items pending now on PMS
- No further belts observed supporting fuel pipes at engine room

The vessel works with ULSFO and LSMGO in order to comply with Sulphur emissions regulations. During the inspection LSMGO was in used for Auxiliary engines and boiler.

HULL DESCRIPTION AND CONDITION:

The antifouling coating and the topside paint were generally found to be in fair to good condition. Several marks and scratches were observed, mainly caused by anchor chains and contact with port fenders. Some areas showed signs of rust. All hull markings were clearly visible, including the Plimsoll and load line marks, the vessel's name, IMO number and port of registry, as well as overboard discharge outlets, tank markings, and the visible sections of the rudder blade and horn. Below level 7m hull was found dirty as shown in pictures. Overall, the condition was considered satisfactory.

DECKS AND SUPERSTRUCTURE DESCRIPTION AND CONDITION:

The equipment and steel structures appeared to be of good quality. Overall maintenance was assessed as fair, significant rust observed in front of the accommodation.

Coatings on the forecastle deck, equipment and piping were found in fair condition, with maintenance activities ongoing. All equipment observed appeared operational and free of leaks. Vents and sounding pipes were also noted to be under active maintenance.

Deck fittings and mooring machinery were found in fair condition, with maintenance in progress and appearing operational. The visible sections of the anchors and chains were unpainted but in good condition. Rollers, bollards, bitts and associated fittings appeared generally operational and free to move.

CARGO SPACES CONDITION:

At the time of the inspection, cargo holds No.1 and No.2 were empty, allowing their internal inspection.

The cargo spaces were generally found in fair to poor condition, with several areas showing rust and corrosion, particularly on cell guides, chains, platforms, ladders, walkways, gratings, supports and associated structures.

Some cell guides were observed with broken welds.

Cargo Holds No.1 and No.2 are fitted with hydraulic folding hatch covers. Their operation was observed to be satisfactory, and no hydraulic leaks were detected in the system.

NAVIGATION BRIDGE:

Bridge and communication equipment were found in good condition and operational. Adequate visibility from the bridge towards the deck was observed.

The VDR has been retrofitted.

The vessel navigates using paper charts only, which were found to be updated.

The deck logbook, error log, GMDSS logbook and passage plans were reviewed and found properly maintained and up to date.

The monkey island was observed in good condition, with all antennas operational and cable penetrations in satisfactory condition. Navigation lights were found in order.

LSA & FFE:

In general, the safety equipment inspected during the onboard attendance was found in good condition, properly marked and ready for use. Documentation related to the control and maintenance of LSA and FFE was reviewed and found complete and up to date, however there was found some places where monthly inspection was not signed for last month.

The rescue boat was observed in good condition and properly maintained. No corrosion or leakages were noted. No signs of excessive deterioration were observed on the hull, and the release system appeared properly prepared. The foundations and crane were also found in good condition.

The free-fall lifeboat engine who was defective last December 2025 was tested during present survey, being found now in fully working order.

Liferafts were installed on both sides of the accommodation block and were noted to be in good condition.

The engine room is fitted with a fixed CO_2 fire extinguishing system. The CO_2 room, cylinders and release system was found in good condition.

The emergency fire pump, driven by an electric motor, was tested and found operational and in good condition.

Remote shut-down systems, fire alarms and smoke detectors were reported to be in proper working order and were found in satisfactory condition.

Fire hoses, hose boxes and hydrants were also noted to be in satisfactory condition.

ENGINE ROOM:

Overall, the engine room was visually observed to be in good condition and well maintained.

As far as could be assessed, pipelines located both above and below the engine room floor plates appeared in satisfactory condition, with no significant leakages or soft patches observed. Oil and fuel tanks were properly marked and fitted with glass level gauges and temperature thermometers, with quick-closing valves found in good order.

The engine room was clean, painted and adequately illuminated, with no slippery areas noted. Firefighting and life-saving equipment were properly marked.

All equipment was clearly identified with the original manufacturer's nameplates. Railings, access ladders, passageways and fire doors were well marked.

Electric motors observed throughout the engine room and other areas of the vessel appeared in good condition and were reported to be operating satisfactorily.

The engine exhaust casing was inspected and found to be clean and in good condition, with no signs of smoke leakage observed.

ACCOMMODATION:

All areas were found clean and well organized. Comfort standards were observed to be in line with European requirements for the construction and arrangement of accommodation and living spaces.

CERTIFICATES and DOCUMENTATION:

All the certificates found in order and updated. Available in hard copies and soft copies.

CONCLUSION:

The M/V **"ATLANTIC GREEN"** was found to be in overall good condition for a vessel of its type and age. However, the condition of the cargo holds could be improved in order to enhance cargo safety, particularly in the areas identified in the deficiency list.

Compared with our previous inspection carried out in December 2025 last year, the overall condition of the vessel remains largely unchanged, and several items identified during that inspection are still pending. Most of these outstanding items are scheduled to be addressed during the next dry-docking, planned for August 2026.

Due to the vessel's trading pattern, involving frequent short voyages and operating mostly in laden condition, the crew has limited opportunities to carry out maintenance work.

ON BOARD MANAGEMENT, CREW MOTIVATION & SAFE WORKING

The onboard management demonstrated effective leadership and good coordination in the vessel's daily operations. Communication between officers and crew was clear and consistent, following established procedures and contributing to an organized and efficient working environment. Crew members appeared motivated, showing a proactive attitude, a cooperative approach and a clear commitment to maintaining operational standards.

Safety procedures were observed to be properly followed, with the crew showing good awareness of risk prevention and safe working practices. Regular safety drills were carried out efficiently, with active participation from all personnel. The overall safety culture on board was found to be positive and progressively improving, ensuring that operations are conducted in a safe and professional manner.

The requirements of SOLAS, MARPOL, MLC and STCW conventions were observed to be properly implemented on board.

The ISM Code, ISPS Code and MLC requirements were also found to be effectively implemented on board.

DEFECTS AND OBSERVATIONS LISTS

DEFECTS LIST		
#	**Item**	**Comment**
01	Rails and walkway	Rust noted. Ordinary Maintenance is to be carried out. PENDING ITEM FROM LAST REPORT
02	Cargo holds	Rust areas in CH3 & 4 need to be maintained. PENDING ITEM FROM LAST REPORT
03	Hold entrance	Rust noted. Ordinary Maintenance is to be carried out. PENDING ITEM FROM LAST REPORT
04	Hatch ladder and walkway	Rust noted. Ordinary Maintenance is to be carried out. PENDING ITEM FROM LAST REPORT
05	Bulkheads	Rust noted. Ordinary Maintenance is to be carried out. PENDING ITEM FROM LAST REPORT
06	Cell guides	Rust noted. Ordinary Maintenance is to be carried out. PENDING ITEM FROM LAST REPORT
07	Void Space	Rust and corrosion noted on the electrical cable way. PENDING ITEM FROM LAST REPORT
08	Void Space	Oil leakages observed from ballast actuator valves. PENDING ITEM FROM LAST REPORT
09	Paint room	Small leakage observed from sprinkler.
10	Accommodation area	No fall prevention means when hatch iwo accommodation is opened for passing spares to engine room.
11	Cell guides	Some welding broken.
12	Fuel Pipes	Several fuel pipes in engine room isolation observed in poor conditions. PENDING ITEM FROM LAST REPORT
13	FPT	Several Anodes supports broken due to corrosion. PENDING ITEM FROM LAST REPORT
14	WBT	Several rust areas and mud observed on ballast water tanks pictures records. PENDING ITEM FROM LAST REPORT
15	Mooring	Brake Test not carried out since last Nov.2021
16	Em. Gen. Room	Gym equipment found on this room, must be solely for emergency power equipment
17	LSA	LSA monthly checking/signature not signed in some places

18	CII	The annual Operational Carbon Intensity Rating for 2024 is E.

OBSERVATIONS LIST		
#	**Item**	**Comment**
01	PMS	Lashing material ordered more than 1 year ago and not received yet on board
02	Hull	Dirty hull from 7m down.
03	Hull	Several scratches and rust areas noted. PENDING ITEM FROM LAST REPORT
04	EPIRB	Battery expires 03.2026.

Kindly be aware, the above quoted costs are estimates only. They may potentially assist with outline CAPEX considerations but should not be used for precise budget purposes. Amounts may vary, depending on various geographical maritime and commercial considerations.

CONSUMPTION SUMMARY

SHIP'S OPERATION	SPEED (Knots)	MACHINERY	T/D	TOTAL T/D
Laden Sea Voyage (With Reefers)	16KNOTS	**Main Engine Auxiliary Engines Boiler**	34.4 MT WITH SHAFT GENERATOR	34.4 MT
Laden Sea Voyage (No Reefers)	NA	**Main Engine Auxiliary Engines Boiler**	28 MT WITH SHAFT GENERATOR	28 MT
Ballast Sea Voyage E.g. Sept 2019 – July 2021	16KNOTS	**Auxiliary Engines Boiler**	28 MT WITH SHAFT GENERATOR	28 MT
In Port at Idle E.g. Sept 2019 – July 2021	NA	**Auxiliary Engines Boiler**	1.5 MT 1.0 MT	2.5 MT
In Port Cargo Operations E.g. Sept 2019 – July 2021	NA	**Auxiliary Engines Boiler**	1.5 MT 1.0 MT	2.5 MT

CARGO HISTORY

DATE	VOYAGE No.	LOADING PORT	DISCHARGE PORT	CARGO	QUANTITY
23.02.2026		CIVITAVECCHIA	SALERMO	CONTAINERS	192
22.02.2026		VADO LIGURE	CIVITAVECCHIA	CONTAINERS	184
19.02.2026		ALGECIRAS	VADO LIGURE	CONTAINERS	289
11.02.2026		SALERMO	ALGECIRAS	CONTAINERS	237
09.02.2026		CIVITAVECCHIA	SALERMO	CONTAINERS	211

VESSELS PARTICULARS

DETAILS	
Name	ATLANTIC GREEN
Previous Name	AMELIE BROCHARD MAX LOYALTY
Owner	SILVER MARITIME EIGHT PTE
Managers	Columbia Shipmanagement Singapore) Pte Ltd
IMO Number	9354404
Flag	SINGAPORE
Port of Registration	SINGAPORE
P & I Insurance Address	UK P&I
H & M Insurance Address	UK P&I
Date of Build	11/08/2006
Ship Builder	JJ SIETAS SCHIFFSWERFT GMBH HAMBURG GE
Hull Number	1239
Type of Vessel	CONTAINER
Classification Society	BV
Classification Notation	I✠ Hull✠ Mach ✠AUT-UMS , INWATERSURVEY
Call Sign	9HA4065
MMSI Number	2449037000

DIMENSIONS		
Summer Deadweight	11432	T
Gross	9962	T
Net	6006	T
Lightship	4315	T
LOA	134.44	M
LBP	124.41	M
Breadth	22.74	M
Depth	11.30	M
Loaded Draught	8.712	M

SUEZ CANAL TONNAGE		
Gross		T
Net		T

PANAMA CANAL TONNAGE		
Net		T

SPARE PARTS

Major Spare Parts	Tailshaft	No
	Propeller	No
	Anchor	No
Main Engine Spare Parts	Cylinder Covers	2
	Cylinder Cover Inserts	NA
	Main Engine Cylinder Liners	1
	Piston and Rod Assembly	1
	Piston Rings	2
	Exhaust Valves Complete	2
	Bottom End Bearing	9
	Set Thrust Pads	0
	Main Bearing	1
	Cross Head Pin	NA
	Cross Head Bearings	NA

SPARE PARTS DESCRIPTION AND CONDITION:

Spare parts in the engine room were found to be properly arranged and securely stored. Items are organized according to their type and frequency of use, with clear labelling allowing easy identification. Storage shelves and lockers were noted to be tidy, unobstructed and maintained in good order. All components were adequately secured to prevent movement during vessel operations. The overall condition of the storage areas reflected good housekeeping practices and compliance with safety standards.

For further reference and the complete spare parts list, please refer to the attached Excel file titled “Critical Spares.pdf.”

VESSEL CONDITION REPORT

1.0 ESG (Environmental – Social – Governance)

1.1 ENVIRONMENTAL: Greenhouse Gas (GHG) Emission Reduction Strategies

OPERATIONAL CARBON INTENSITY INDICATOR (CII) RATING	FINDING	COMMENTS
Onboard approved and compliant SEEMP Part III Decarbonisation Plan (re-verification of Plan required every 3 years - after 01st January 2023).	Yes	
Onboard Data Collection System (DCS) reporting system and valid Statement of Compliance (SoC).	Yes	
Verified Operational CII Grade (include year of calculation – as per certificate)	Yes	Rate E calculation for year 2024

ENERGY EFFICIENCY for EXISTING SHIP INDEX (EEXI)	FINDING	COMMENTS
Required EEXI Rate (applies to vessels >400GRT)	25.1 gCO2/t.nm	As per approved IEEC
Attained EEXI Range (include year of calculation – as per certificate)	25.1 gCO2/t.nm	As per approved IEEC

ENERGY EFFICIENCY DEVICES / TECHNOLOGY FITTED: HULL / EXTERNAL	FINDING	COMMENTS
Hull Coating (Low-Coefficient)	No	
Last Anti-foul Application (Date & Age)	Yes	Last DD, NOV 2021
Last Hull Cleaning Date (If Applicable)	Yes	13.10.2024
Fitted Hull Fuel Enhancing Features	No	

ENERGY EFFICIENCY DEVICES / TECHNOLOGY FITTED: ENGINES	FINDING	COMMENTS
Overridable Engine Power Limitation (EPL) or Shaft Power Limitation (SHaPoLi) Fitted Revised Output: Date of Implementation: Certificate Issuance Date:	Yes 7200 kW 500RPM	

	29.01.2024	
Optimised Fuel Economy Device (e.g. Leanmarine)	No	
Main Engine Carbon Emission Reduction Fittings - Exhaust Gas Recirculation (EGR) - Cylinder Oil Optimisation (ie Alfa Lubricators) - Fuel Injection Optimisation (ie Injectors, Fuel Pump)	 No No No	
Other Devices – Description	N/A	

ENERGY EFFICIENCY SOLUTIONS: FUEL / BATTERY / TECHNOLOGY MODIFICATIONS	FINDING	COMMENTS
Fuels in Use	Yes	ULSFO & LSMGO <0.1% SULPHUR
Methanol	No	
Other Biofuel Types	No	
Gas: LNG / LPG / Ammonia / Hydrogen	No	
Battery System	No	
Shore-side Connection	No	
Improved Route Planning Software installed (if YES – give details)	No	
Carbon Capture and Storage (CCS) considerations	No	
Other Devices – Description	No	

1.2 ENVIRONMENTAL: Other Applicable Environmental Observations

	FINDING	COMMENTS
Has the vessel a **Ballast Water Treatment Plan (BWTP)** - BWT System Description (UV, Electrolysis, Filtration, Chemical Dosing etc) - USCG Approval	Yes Yes	BWTP UV system in good working conditions. Alfa-Laval Type: PureBallast 3.2 Compact Flex
Has the vessel an **Inventory of Hazardous Material (IHM)** Certificate - Details of any other IHM related compliance documentation - Does Vessel Hold Asbestos Free Certification	Yes Yes	Statement of compliance and international certificate on IHM according to Hong Kong convention and EU regulation available on board.
Has the vessel a **Sewage Treatment Plant** - Sewage Holding Tank Fitted - Sewage Treatment System Description eg Biological and / or Chemical (NaCl or NaCl and NaHS04)	Yes Yes	Sewage treatment plant Biological in good working order.
Has the vessel an **Oil Water Separator(s) OWS** Fitted / Approved - OWS Description - OWS Description eg. compliance with MEPC.60(33) – In force up to 2005 (Alarm and Stop) or MEPC.107(49) – In Force for Vessels after 2005 (Alarm / Three-way valve / Recirculation).	Yes	OWS 15 PPM alarm installed and three way valve operative. Overboard valve locked and sealed.
Has the vessel an **Incinerator** (in compliance with MARPOL Annex VI, Regulation 16)	No	
Stern Tube (and Bow/Stern Thruster & CPP) Environmentally Acceptable Lubricants (EAL) - Meets EALs Standard Oil in Use (Type) - Water Based Stern Tube Lubrication - Air Seal Arrangement (Air Seals working with non-EAL are considered as alternative to EAL use by EPA, in principle)	No	
US EPA **Vessel General Permit (VGP)** Compliant - Certificate (not) provided. The vessel is (not) compliant with USCG Vessel General Permit (VGP) for discharges incidental to the normal operation of the vessel.	No	
Has the vessel an **Oil Discharge Monitoring Equipment (ODME)** Fitted - Approved Type – Annex I - Approved Type – Annex II	N/A	Applicable to oil tankers only
Has the vessel a **Garbage Management Plan Fitted** - Is Garbage Segregation Implemented Effectively and is the Garbage Record Book Completed and Up to Date - Last Garbage Shore Discharge Date (taken from Garbage Record Book)	Yes Yes 05.03.2026 Yes	

- Are all entries signed by Officer in Charge - Are Receipts for Discharging Garbage Ashore Retained	Yes	
Are Measures in Place to Reduce Single Use Plastics Onboard. I.E Water Bottles	Yes	
Has the vessel a **Marine Casualties Record** file onboard	Yes	No marine casualties on records.

1.3 SOCIAL: Health, Safety and Security Observations

	FINDING	COMMENTS
IMO ISM Code Safety Management System (SMS) being implemented effectively onboard	Yes	
ISO 45001 (Occupational Health and Safety Management System) being effectively implemented onboard	Yes	
Good / hygienic catering and enhanced dietary selection available to all crew	Yes	
Modern and reliable Wi-Fi facilities available to all crew - Free Unlimited / Free Limited / Paid limited - Speed (Fast / Medium / Slow)	Yes	Medium speed
Good access to Bonded Store to all crew	Yes	
Are Drills Conducted as Per Company SMS	Date:	Drill Type:
	Fire	17.FEB.2026
	Abandon	17.FEB.2026
	Enclosed space	09.JAN.2026
Adequate onboard crew training available - Training Software Vendor	Yes	
Structured periods of rest being implemented and adhered to	Yes	
Level of crew wellbeing and morale	Good	
Sufficient levels of safety and medical PPE available for crew? e.g. FFP2 masks, gloves etc.	Yes	

Level of available onboard medical treatment and mental health support	Yes	
Condition of the onboard Hospital and medical equipment / supplies	Good	Hospital ready for use. No expired medicines on board.
Has the vessel a crew **Incidents / Accidents Record** - Reported Lost Time Incidents (LTI's) / Casualties over last 12 months - If Yes – Details of reported Lost Time Incidents (LTI's) / Casualties	No	
Structured Crew Recruiting Policy and Procedures being adhered to onboard. Structured crew career development Policy / Procedures	Yes Yes	
Crew shoreside communication access facilities	Yes	
Onboard fitness facilities	Yes	Located in emergency generator room due to limited recreation space.

1.4 GOVERNANCE: Onboard observations

	FINDING	COMMENTS
Labour Rights and Diversity of the Workforce Policy and Procedures are visible and being correctly implemented onboard.	Yes	
Business Ethics Policy and Procedures being adhered to onboard. i.e. code of conduct, anti-corruption, bribery, whistleblowing etc.	Yes	
Cyber Security Policy and Procedures being adhered to onboard.	Yes	
Onshore independent employment and legal support services available to all crew.	Yes	
Marine Sustainability / Protection Policy and Procedures being adhered to onboard	Yes	

SECTION 2: ACCOMMODATION

No.	Item	VERY GOOD	GOOD	FAIR	POOR	UNSATIS-FACTORY	Comment
2-1	General appearance		✓				General good appearance, clean and tidy.
2-2	Accommodation entrances secured / locked		✓				Accommodation entrances secured and locked where necessary.
2-3	Entrance doorbell and code lock		✓				
2-4	Fire doors		✓				Well maintained and self-closing properly.
2-5	Restricted areas marked and secured		✓				Restricted areas well marked.
2-6	Posters clearly displayed		✓				
2-7	Muster lists		✓				Muster lists available in all concerned areas.
2-8	Safety signage		✓				
2-9	LSA/FFA Training manuals		✓				Manuals located in designated areas and signed by all crew.
2-10	Code of Safe Working Practices		✓				
2-11	Video-Tel VOD – Complete Set						NA
2-12	Cabins Inspected		✓				Cabins in good conditions of maintenance.
2-13	Public Toilets, Changing rooms			✓			Operative and in order.
2-14	General appearance of Galley			✓			Galley found in order, free of infestation and clean.
2-15	Hygiene and cleanliness		✓				

2-16	Food rotation		✓				Good provisions supply observed.
2-17	Fridges and freezers cleaning schedule		✓				
2-18	Fridge alarms & lock-in devices		✓				
2-19	Garbage segregation		✓				Garbage segregated as required
2-20	Garbage Disposal Placards		✓				
2-21	General appearance of Hospital		✓				Hospital well maintained. Oxygen and two masks ready for use as IMDG code requirement.
2-22	Hospital alarm		✓				
2-23	Breathalyzer kits /Alcohol tester		✓				
2-24	Medical locker		✓				Medicines well stored and controlled
2-25	Semi-Automatic External Defibrillator		✓				Located in hospital.
2-26	General appearance of Laundry		✓				
2-27	Iron - not left unattended and notice posted		✓				
2-28	Washing Machines, Dryers and exhausts clean and free of lint		✓				Washing machines operatives.

SECTION 3: INSPECTIONS AND SURVEY STATUS

No.	Item	VERY GOOD	GOOD	FAIR	POOR	UNSATIS-FACTORY	Comment
3-1	Vessel Certificates & Survey Status	✓					No certificates expired or overdue surveys.
3-2	Last Supers Inspection Outstanding Items		✓				
3-3	Last Vetting /PandI Inspections Outstanding Items	✓					
3-4	Port / Flag State Inspection Outstanding Items						Last PSC on 14.10.2025 without deficiencies. No flag inspection on records.
3-5	Defects Reports Status	✓					

SECTION 4: BRIDGE EQUIPMENT

No.	Item	VERY GOOD	GOOD	FAIR	POOR	UNSATIS-FACTORY	Comment
4-1	Bridge Navigational Watch Alarm System		✓				
4-2	General Alarm and Fire Alarm		✓				
4-3	Bridge Emergency Main Engine Shut Down		✓				
4-4	Aldis Lamp (including 3 spare bulbs)		✓				Working properly from direct power and battery

4-5	Ship's Whistle		✓				
4-6	Oxygen/Gas Meter and test tubes		✓				
4-7	3 Oxygen Meters		✓				
4-8	Multi Gas detector kit (with 25m hose)		✓				
4-9	Ship’s Bell Min Diam 300mm		✓				
4-10	Magnetic Compass		✓				
4-11	Gyrocompass & Repeaters		✓				

SECTION 5: BRIDGE & DECK LOGBOOK

No.	**Item**	**VERY GOOD**	**GOOD**	**FAIR**	**POOR**	**UNSATIS-FACTORY**	**Comment**
5-1	Watchkeeping Arrangements (Lookout)		✓				
5-2	Regular Position fixes on charts during navigation (maximum 1hr interval)		✓				
5-3	Daily watch keeping entries		✓				
5-4	Steering Gear Test prior to arrival / departure		✓				
5-5	Safety and Security Rounds		✓				
5-6	Hose tests of hatch covers recorded		✓				

SECTION 6: DECK SAFETY & SECURITY

No.	Item	VERY GOOD	GOOD	FAIR	POOR	UNSATIS-FACTORY	Comment
6-1	Emergency exits and escape Sets (EEBD)		✓				Free of obstructions and recovery person items duly stowed
6-2	Fire flaps and dampers		✓				Operative and closing totally (manually)
6-3	Portable fire extinguishers and refills		✓				Properly stowed, ready for use and no overdue inspections.
6-4	Emergency fire pump		✓				Operative
6-5	Fire line deck isolation valve		✓				Free to move and closing completely
6-6	International shore connection + 2 sets of rubber packing, 4 complete bolt/nuts (M24) with 2 spring washers and two ring type M24 spanners		✓				
6-7	Lifeboat and contents		✓				Satisfactorily tested
6-8	Lifejackets / Immersion suits & storage boxes		✓				Lifejackets in good conditions.
6-9	Smoke floats and lifebuoys		✓				
6-10	EPIRBs		✓				HRU exp date: 07/2027 Batt exp date: 03/2026
6-11	Muster Point identified		✓				
6-12	Emergency exits clear and secured		✓				Emergency exits properly marked, well illuminated and without obstructions.
6-13	Fire Plans and tube (with IMDG Cargo & Crew List)		✓				In order and crew list updated
6-14	Water-tight doors and covers		✓				

6-15	Rescue boats and contents		✓				
6-16	Outboard motor + 2 rubber impellers, 1 spark plug as a minimum spare + KILL CORD on the RB		✓				
6-17	Davits and release mechanisms		✓				
6-18	Observe LR / RB crane and LB davit test (Observe backup power & limit switches in order)		✓				
6-19	Life rafts and embarkation ladders		✓				Last service: 05/2025
6-20	Fireman outfits and BA sets		✓				
6-21	Chemical suits (IMDG only)		✓				
6-22	Safety rails and walkways				✓		Corrosion noted in several items. Refer to defect list
6-23	Fire hoses and boxes		✓				Properly stowed and ready for use.
6-24	Forecastle areas secured unless manned		✓				

SECTION 7: GENERAL HULL & DECK

No.	Item	VERY GOOD	GOOD	FAIR	POOR	UNSATIS-FACTORY	Comment
7-1	Ship's General Appearance			✓			Several rust areas identified, refer to defect list.
7-2	Current Hull Coating Condition			✓			Several scratches and rust spots noted.
7-3	Hull Visible Premature Corrosion and Marine Growth			✓			See remarks, hull below 7m dirty
7-4	Name, IMO, Draughts and Port of Registry		✓				Properly marked and well visible.

7-5	Forecastle general appearance			✓			Maintenance still in progress
7-6	Bosun's store general appearance		✓				
7-7	Paint locker general appearance		✓				
7-8	Windlass		✓				Operative and no leakages observed.
7-9	Capstan		✓				
7-10	Ropes and fenders		✓				
7-11	SOPEP locker		✓				Locker in order.
7-12	Acetylene bottles		✓				Properly secured.
7-13	Oxygen bottles		✓				
7-14	Pilot ladder		✓				Good conditions.
7-15	Gangways		✓				Painted, SWL and max angle well marked.
7-16	Waste bins		✓				
7-17	Anchor operation observed		✓				
7-18	Mast wire stays		✓				
7-19	PMS- Review of MESPAS tasks & defects		✓				

SECTION 8: CARGO / HATCHES / HOLDS

No.	Item	VERY GOOD	GOOD	FAIR	POOR	UNSATIS-FACTORY	Comment
8-1	Hatch general condition		✓				
8-2	Hold general condition			✓			Several corrosion and rust areas identified, refer to defect list.
8-3	Hatch entrances clear and secured			✓			Refer to defect list.
8-4	Hatch ladders and walkways				✓		Corrosion noted
8-5	Hatch tools and loose equipment		✓				
8-6	Hatch operation observed		✓				
8-7	Hold ventilation and lighting			✓			
8-8	Bulkheads / tween decks			✓			
8-9	Bilge sounding points / pumps			✓			
8-10	Dehumidifiers						NA
8-11	Stores Lockers Compartments						NA
8-12	Gantry or cargo cranes operation observed						NA
8-13	Crane operators' cabin						NA
8-14	Crane safety devices						NA
8-15	Cargo Holds cleaning equipment						NA
8-16	Hatch coamings drain valves			✓			
8-17	Hatch Covers Resting pads			✓			
8-18	Cell Guides				✓		Corrosion noted

8-19	Reefer Sockets			✓			
8-20	Tween Decks (If Applicable)						NA
8-21	PPE in use, RAs in use, Work permits in use		✓				Permit issued to inspected ballast tanks

SECTION 9: ENGINE ROOM GENERAL

No.	Item	VERY GOOD	GOOD	FAIR	POOR	UNSATIS-FACTORY	Comment
9-1	Engine Room General Appearance		✓				Illuminated, painted and clean
9-2	Tools and Equipment Stowed		✓				
9-3	Rag/Metal/Waste Bins		✓				Properly disposed
9-4	Strops/Chain Blocks and Overhead Crane		✓				
9-5	Ballast System Plan		✓				Fitted, vessel approved for D-2, BWTP in order
9-6	Posters and signage		✓				
9-7	Stores stowed and secured		✓				
9-8	Oil Transfer Procedure available and posted		✓				
9-9	PMS- MESPAS review of Tasks & Defects		✓				
9-10	PPE in use, RAs in use, Work permits in use		✓				

SECTION 10: ENGINE CONTROL ROOM

No.	Item	VERY GOOD	GOOD	FAIR	POOR	UNSATIS-FACTORY	Comment
10-1	General Appearance		✓				
10-2	UMS Alarm in use and tested (If Applicable)		✓				In use. UMS panel located on engineer's cabins, mess room and bridge.
10-3	Communication between bridge and engine room		✓				
10-4	Switchboard with rubber mat		✓				Rubber mats distributed in all electrical control panels.
10-5	Start / Stop procedures for main engine and equipment		✓				
10-6	Chief Engineer's Orders posted		✓				
10-7	Company Standing Orders posted.		✓				

SECTION 11: ENGINE ROOM LOGBOOK & OIL RECORD BOOK

No.	Item	VERY GOOD	GOOD	FAIR	POOR	UNSATIS-FACTORY	Comment
11-1	Times of UMS recorded (if applicable)		✓				
11-2	Daily watchkeeping/work arrangements		✓				
11-3	Time / Vessel position of changeover of fuels. Correct and proper recording in Marine Fuel Sulphur Record Book (MFSRB) contained in		✓				Vessel only consumes ULSFO (Main engine) & LSMGO (Auxiliary engines) < 0.1% Sulphur content

	the Emissions Control Manual. For ECA zones and EU ports.						
11-4	Stern tube temperatures and LO consumption recorded		✓				
11-5	Oil record Book checked		✓				Updated, properly filled.

SECTION 12: ENGINE ROOM EQUIPMENT

No.	Item	VERY GOOD	GOOD	FAIR	POOR	UNSATIS-FACTORY	Comment
12-1	Alarms and shutdowns		✓				
12-2	Bilge pumps		✓				
12-3	Oily water separator		✓				Operative, Overboard valve sealed and secured.
12-4	Ballast valves operated monthly		✓				
12-5	Indicator gauges and lights		✓				
12-6	Hydraulics		✓				No leakages observed
12-7	Electrics		✓				No electric faults observed
12-8	Pipes and fittings			✓			Some pipelines insulation dirty / soaked.
12-9	Main engine and appendages		✓				
12-10	Shaft generator		✓				Working properly
12-11	Auxiliary engines		✓				Operatives, no leakages observed.
12-12	Boiler plant		✓				Thermal oil boiler in good working order.
12-13	Incinerator						NA

12-14	Domestic plants		✓				
12-15	Pumps / compressors		✓				Operatives.
12-16	Heaters / coolers		✓				No leakages noted.
12-17	Filters		✓				
12-18	Fire pumps		✓				In good working order
12-19	Remote sounding system		✓				
12-20	Fuel treatment plant		✓				No leakages noted.
12-21	Smoke extraction system		✓				
12-22	Test emergency pitch control		✓				CPP in order
12-23	Check M.E oil mist detector		✓				Operative.
12-24	Check stand-by purifiers in working order		✓				No leakages observed. Good working order.
12-25	OWS meter calibration		✓				

SECTION 13: ENGINE ROOM EQUIPMENT

No.	Item	VERY GOOD	GOOD	FAIR	POOR	UNSATIS-FACTORY	Comment
13-1	Emergency bilge suction valve		✓				
13-2	Emergency main engine shut down		✓				
13-3	Emergency lighting		✓				
13-4	Safety rails and floor plates secure		✓				Safety rails properly marked and painted.
13-5	Emergency escapes accessible		✓				Free of obstructions and properly identified

13-6	All escapes secured as per instruction		✓				
13-7	Safety equipment accessible		✓				
13-8	CO2 pre-warning alarm		✓				
13-9	Fire pump		✓				
13-10	Quick closing valves		✓				Panel located in the entrance of engine control room.
13-11	Machinery / fan remote stops		✓				
13-12	Main engine local stops		✓				
13-13	Water mist system		✓				Located in engine room workshop in AUTO mode without alarms.
13-14	Fixed CO2 system		✓				For E/R and cargo holds.
13-15	Critical equipment list clearly identified, maintenance up to date, spare parts available		✓				

SECTION 14: STEERING GEAR

No.	Item	VERY GOOD	GOOD	FAIR	POOR	UNSATIS-FACTORY	Comment
14-1	Steering Gear		✓				In good working operation
14-2	Hydraulics		✓				No leakages observed
14-3	Steering Room		✓				

SECTION 15: EMERGENCY GENERATOR ROOM

No.	Item	VERY GOOD	GOOD	FAIR	POOR	UNSATIS-FACTORY	Comment
15-1	General appearance			✓			Gym equipment found on EG room
15-2	Back-up / start /test under load observed or last date checked		✓				
15-3	Fuel tank full and frequently drained		✓				Fuel tank level in order, QCV operative.
15-4	Emergency lighting marked and tested		✓				
15-5	Emergency switchboard rubber matting		✓				
15-6	Start procedure from dead ship posted		✓				

SECTION 16: BUNKERS & SAMPLES

No.	Item	VERY GOOD	GOOD	FAIR	POOR	UNSATIS-FACTORY	Comment
16-1	HFO / IFO Fuel Sampling Records (As per Lintec and MARPOL A-VI;)		✓				
16-2	Save-Alls empty & with all fittings		✓				
16-3	Oils/Sludge Transfer/Line Diagram Posted		✓				
16-4	Sample Bottles / Cubitainer available		✓				
16-5	Designated storage for samples		✓				
16-6	Water finding paste		✓				

16-7	Bunker / safety pollution prevention procedures		✓				

SECTION 17: BALLAST TANKS

No.	Item	VERY GOOD	GOOD	FAIR	POOR	UNSATIS-FACTORY	Comment
17-1	Ballast Tanks Inspected	FPT					Forepeak in fair-good conditions with some rust areas.
17-2	Condition of Manhole/Access			✓			
17-3	Condition of Stringer Deck Plating		✓				
17-4	Condition of Web Frames		✓				
17-5	Condition of Inner Shell Plating		✓				
17-6	Condition of Double Bottom		✓				
17-7	Condition of Pipelines and Bell Mouth		✓				
17-8	Is There Mud or Other Contaminants?			✓			Some mud observed on forepeak tank and WBT photos records.
17-9	Percentage Intact of Anodes			✓			50%
17-10	Deformations to Scantlings		✓				
17-11	Condition of Ballast Pumps		✓				
17-12	Condition of BWTS		✓				
17-13	Condition of Heeling Pumps		✓				Operative and working at time of inspection

Section 18: Lashing Gear Remaining Onboard

#	Type	Quantity
1	Bottom stacking cones	248
2	Lockable stacking cones	650
3	Twist lock	522
4	Cellguide twistlocks	30 right / 36 left
5	Turnbuckle Jaw & Knob	179
6	Lashing bars	142+30+26
7	Midlock stacker	370
8	Extension rod	NA 1-8bins
9	20 feet flat rack with 8 bins	
10	Distant cone	4
11	Condition of Lashing Gear	Fair-Good

BACKPIECE

Clients are respectfully reminded that this report is the product of a Superficial Inspection conducted 'against the clock'. Whilst we are of the opinion that we have established the overall condition of the vessel, it should be borne in mind that much of the internal structure has not been entered and that the majority of equipment was not working during the inspection. Any estimated costs of repairs or opinions expressed in this report are subjective by the attending surveyor and without prejudice to the interests of any or all of the parties concerned.

This is a Copyright report produced by Aalmar Surveys Ltd. for client's exclusive use.

This report is intended for the sole use of the person to whom it is addressed and no liability, of any nature whatsoever, shall be assumed to any other party in respect of its contents. As to the addressee, neither 'Aalmar Surveys Ltd.' nor the undersigned shall be liable for any loss or damage whatsoever suffered by virtue of any act, omission or default (whether arising by negligence or otherwise) by the undersigned, 'Aalmar Surveys Ltd.' or any of its servants.

Full terms and conditions are available on our website at www.aalmar.com

Please contact us if you are interested in any of the other services we offer:
Sale Handover Supervision | Dry-docking Cost Estimates | Class Records Searches | Owners Condition Surveys | ISM Related Audits.

REFERENCE:	ISSUE:	REVISION:	DATE:
ASL/SAL/P15/F03	1	10	18.07.2024

REPORT CHECKED BY:	
Name: Glendovere Gado	**Signature:**

Aalmar
WORLDWIDE MARINE SURVEYS
1 Exchange Building | 132 Commercial Street | London | E1 6NG | UK
TEL +44 (0) 207 923 2815 **EMAIL** info@aalmar.com **WEB** www.aalmar.com
An ISO9001:2015 Certified Company - Bureau Veritas Cert. No. MER19.270/UQ