

press motor mount

this drawing is by no means accurate to dimensions and should only be used as the basis for an understanding as to swhat needs to be fabricated.

assume that it is made from 1/2 plate iron.

the most critical dimension will be the size and placement of the two slots on the top through which the motor mounting bolts will secure the motor to the base. this dimension can only be ascertained when one has possession of the motor to be mounted.

side

