

Assembly

Bottom plate

1.



2.




place IR board (fix with tape)

screw in board

place switch


3.



connect wire from raw pin on the board to bottom pin of the switch (can be fixed with heatsock)

plug in battery


4.



connect another wire from the 2nd pin of the switch, which will power the servos


Chassis

5.




screw in servos

6.




screw on top of bottom plate

7.




plug in servo shield

8.




plug in
left servo (0)
servo power (middle, any)
right servo (5)
(example pins)



(can wrap wires around battery holder)


Top case

9.




Screw in mirror servo with gear

10.




plug in servo (7)

11.



place battery on battery holder

12.



place mirror adapter and mirror