| Обозначение резьбы Диаметр отверстия, мм Обозначение резьбы Диаметр отверстия, мм M 1.1 0.75 M 10 8 M 1.2 0.95 M 12 1 M 1.2 0.95 M 12 1 M 1.4 1.1 M 14 1 M 1.8 1.25 M 16 1 M 2.2 1.6 M 22 1 M 2.5 2.05 M 24 2 M 3.5 2.5 M 30 2 M 3.5 2.9 M 30 2 M 4.5 3.3 M 33 2 M 4.5 3.3 M 36 3 M 5.0 M 3.9 2 3 M 4.5 3.3 M 36 3 M 5.0 M 45 M 45 4 M 7 6.0 M 45 4 M 9 7.7 M 52 4 | | | Sheeti | |
|--|--------------------|-----------------------|--------------------|-----------------------|
| 0.75 M 10 0.85 M 11 0.95 M 12 1.1 M 14 1.25 M 16 1.45 M 18 1.6 M 20 1.75 M 24 2.05 M 24 2.5 M 27 2.9 M 30 3.3 M 36 4.2 M 36 5.0 M 42 6.0 M 45 6.0 M 45 7.7 M 52 | Обозначение резьбы | Диаметр отверстия, мм | Обозначение резьбы | Диаметр отверстия, мм |
| 0.85 M 11 0.95 M 12 1.1 M 14 1.25 M 16 1.45 M 18 1.6 M 20 1.75 M 22 2.05 M 24 2.9 M 30 3.3 M 33 4.2 M 38 6.0 M 45 6.0 M 45 6.7 M 48 7.7 M 52 | M 1 | 0.75 | M 10 | 8.5 |
| 0.95 M 12 1.1 M 14 1.25 M 18 1.45 M 20 1.6 M 20 2.05 M 24 2.9 M 30 2.9 M 30 3.3 M 36 4.2 M 36 5.0 M 42 6.0 M 45 6.0 M 48 7.7 M 52 | M 1.1 | 0.85 | M 11 | 9.5 |
| 1.25 M 14 1.25 M 18 1.6 M 20 1.75 M 24 2.05 M 24 M 27 M 27 2.9 M 33 3.3 M 36 4.2 M 36 5.0 M 42 6.0 M 45 6.7 M 48 7.7 M 52 | M 1.2 | 0.95 | M 12 | 10.2 |
| 1.25 M 16 1.45 M 18 1.6 M 20 1.75 M 22 2.05 M 24 2.9 M 30 3.3 M 33 4.2 M 36 5.0 M 42 6.0 M 45 6.7 M 48 7.7 M 52 | M 1.4 | 3 | M 14 | 12.0 |
| 1.45 M 18 1.6 M 20 1.75 M 22 2.05 M 24 M 27 M 27 2.9 M 30 3.3 M 33 4.2 M 36 5.0 M 42 6.0 M 45 6.7 M 48 7.7 M 52 | M 1.6 | 1.25 | M 16 | 14.0 |
| 1.6 M 20 1.75 M 22 2.05 M 24 2.5 M 27 2.9 M 30 3.3 M 33 4.2 M 36 5.0 M 42 6.0 M 45 6.7 M 48 7.7 M 52 | M 1.8 | 1.45 | M 18 | 15.4 |
| 1.75 M 22 2.05 M 24 2.9 M 30 3.3 M 33 4.2 M 36 5.0 M 42 6.0 M 45 6.7 M 48 7.7 M 52 | M 2 | 1.6 | M 20 | 17.4 |
| 2.05 M.24 2.5 M.27 2.9 M.30 3.3 M.33 4.2 M.36 5.0 M.42 6.0 M.45 6.7 M.48 7.7 M.52 | M 2.2 | 1.75 | M 22 | 19.4 |
| 2.5 M 27 2.9 M 30 3.3 M 33 4.2 M 39 5.0 M 42 6.0 M 45 6.7 M 48 7.7 M 52 | M 2.5 | 2.05 | M 24 | 20.9 |
| 2.9 M 30 3.3 M 33 3.8 M 36 4.2 M 39 5.0 M 42 6.0 M 45 6.7 M 48 7.7 M 52 | M 3 | 2.5 | M 27 | 23.9 |
| 3.3 M 33 3.8 M 36 4.2 M 39 5.0 M 42 6.0 M 45 6.7 M 48 7.7 M 52 | M 3.5 | 2.9 | M 30 | 26.4 |
| 3.8 M 36 4.2 M 39 5.0 M 42 6.0 M 45 6.7 M 48 7.7 M 52 | M 4 | 3.3 | M 33 | 29.4 |
| 4.2 M 39 5.0 M 42 6.0 M 45 6.7 M 48 7.7 M 52 | M 4.5 | 3.8 | M 36 | 31.9 |
| 5.0 M 42 6.0 M 45 6.7 M 48 7.7 M 52 | M 5 | 4.2 | M 39 | 34.9 |
| 6.0 M 45 6.7 M 48 7.7 M 52 | | 5.0 | M 42 | 37.4 |
| 6.7 M 48 7.7 M 52 | M 7 | 6.0 | M 45 | 40.4 |
| 7.7 M 52 | M 8 | 6.7 | M 48 | 42.8 |
| | 6 W | 7.7 | M 52 | 46.8 |