

MUSTERİ: Soner Beyazıt

PLAKA: 35 FSM 1453

ISO 7638 VOLTAJ TEST

PIN	Adi	Normal	Okunan	Durum
PIN 1	AKU	24V	0.0V	PENDING
PIN 2	KONTAK	24V	0.0V	PENDING
PIN 3	SASE	24V	0.0V	PENDING
PIN 4	SASE	24V	0.0V	PENDING
PIN 5	ABS	24V	0.0V	PENDING
PIN 6	CAN H	24V	0.0V	PENDING
PIN 7	CAN L	24V	0.0V	PENDING

Teknisyen Notu: Hic biri calismiyor

ISO 12098 VOLTAJ TEST

PIN	Adi	Normal	Okunan	Durum
PIN 1	SOL SINYAL	24V	---V	PENDING
PIN 2	SAG SINYAL	24V	---V	PENDING
PIN 3	ARKA SIS	24V	---V	PENDING
PIN 4	SASE	24V	---V	PENDING
PIN 5	SOL PARK	24V	---V	PENDING
PIN 6	SAG PARK	24V	---V	PENDING
PIN 7	STOP LAMBASI	24V	---V	PENDING
PIN 8	GERI VITES	24V	---V	PENDING
PIN 9	SUREKLI +24V	24V	---V	PENDING
PIN 10	BALATA ASINMA	24V	---V	PENDING
PIN 11	FREN SISTEMI	24V	---V	PENDING
PIN 12	DINGIL KALDIRMA	24V	---V	PENDING
PIN 13	SASE	24V	---V	PENDING
PIN 14	CAN H	24V	---V	PENDING
PIN 15	CAN L	24V	---V	PENDING

Teknisyen Notu: 12098 soket takili voltaj gelmiyor kablo kopuk soket kırık

ISO 7638 KABLO TEST

PIN	Adi	Durum
PIN 1	AKU	FAIL
PIN 2	KONTAK	FAIL
PIN 3	SASE	FAIL
PIN 4	SASE	FAIL
PIN 5	ABS	FAIL
PIN 6	CAN H	FAIL
PIN 7	CAN L	FAIL

Teknisyen Notu: 7638 kablo komple bozuk

ISO 12098 KABLO TEST

PIN	Adi	Durum
PIN 1	SOL SINYAL	FAIL
PIN 2	SAG SINYAL	FAIL
PIN 3	ARKA SIS	FAIL
PIN 4	SASE	FAIL
PIN 5	SOL PARK	FAIL
PIN 6	SAG PARK	FAIL
PIN 7	STOP LAMBASI	FAIL
PIN 8	GERI VITES	FAIL
PIN 9	SUREKLI +24V	FAIL
PIN 10	BALATA ASINMA	FAIL
PIN 11	FREN SISTEMI	FAIL
PIN 12	DINGIL KALDIRMA	FAIL
PIN 13	SASE	FAIL
PIN 14	CAN H	FAIL
PIN 15	CAN L	FAIL

Teknisyen Notu: 12098 soketler degisecek

LAMBA TEST

Lamba	Durum
SAG SINYAL	OK
SOL SINYAL	OK
SAG SINYAL	OK
SOL SINYAL	OK

Lamba	Durum
ARKA SIS	OK
SOL PARK	OK
SAG PARK	OK
GERI VITES	OK
STOP LAMBASI	OK

TESHIS VE SONUC

Hersey bozuk tesisat yenilenecek

75.000 TL+KDV