Curve fitting, regression and optimization

Dr.ir. Ivo Roghair, Prof.dr.ir. Martin van Sint Annaland

Chemical Process Intensification group Eindhoven University of Technology

Numerical Methods (6E5X0), 2020-2021

Today's outline

Introduction •O

- Introduction
- Curve fitting
- Regression
- Fitting numerical models
- Optimization
- Linear programming
- Summary



Overview

0

- We are going to fit measurements to models today
- You will also learn what R^2 actually means
- We get introduced to constrained and unconstrained optimization.
- We will use the simplex method to solve linear programming problems (LP)



Today's outline


- Introduction
- Curve fitting
- Regression
- Fitting numerical models
- Optimization
- Linear programming
- Summary



Let's do an 'experiment' to gather data



Fitting models to data





How to fit a model to the data?

We would like to fit the following model to the data:

$$\hat{y} = a_1 + a_2 x + a_3 x^2 + a_4 x^3$$

First step: If we have N data points, we could write the model as the product of a matrix and a vector:

$$\begin{bmatrix} \hat{y}_1 \\ \hat{y}_2 \\ \hat{y}_3 \\ \vdots \\ \hat{y}_N \end{bmatrix} = \begin{bmatrix} 1 & x_1 & x_1^2 & x_1^3 \\ 1 & x_2 & x_2^2 & x_2^3 \\ 1 & x_3 & x_3^2 & x_3^3 \\ \vdots & \vdots & \vdots & \vdots \\ 1 & x_N & x_1^2 & x_2^3 \end{bmatrix} \begin{bmatrix} a_1 \\ a_2 \\ a_3 \\ a_4 \end{bmatrix}$$

$$\hat{y} = Xa$$

X is called the design matrix and a are the fit parameters.



Residuals

Second step: work out the residuals for each data point:

$$d_i = (y_i - \hat{y}_i)$$

Third step: work out the sum of squares of the residuals:

$$SSE = \sum_{i} d_i^2 = \sum_{i} (y_i - \hat{y}_i)^2$$

This can be written using the dot-product operation:

$$SSE = \sum_{i} d_{i}^{2} = d \cdot d = d^{T} \cdot d = (y_{i} - \hat{y}_{i})^{T} \cdot (y_{i} - \hat{y}_{i})$$



Minimizing the sum of squares

Choose the parameter vector such that the sum of squares of the residuals is minimized; the partial derivative with respect to each parameter should be set to zero:

$$\frac{\partial}{\partial a_i} \left[\left(y - (Xa)^T \right) (y - Xa) \right]$$

In Matlab, we can solve our linear system $\hat{Y} = Xa$ simply by running a = x\y.


- If there are more data points (N > 4), we can write an analogue, but maybe a consistent solution does not exist (the system is over specified).
- However, matlab will find values for the vector a which minimize $||y aX||^2$, so i.e. a least squares fit.



Fitting our problem: Matlab solver

As a follow-up of the script provided in slide 345

```
N=length(x);
X(:,1) = ones(N,1);
X(:,2) = x;
X(:,3) = x.^2;
X(:,4) = x.^3;
A = X\y';
```





Fitting our problem: Matlab curve-fitting toolbox

- Start the toolbox: cftool
- Choose the dataset (x and y data)
- Choose the interpolant type (polynomial, exponential, ..., custom)
- Get the coefficients (save to workspace or write them down)




Fitting our problem: Excel

- Create a column with the independent and dependent data series (x and y)
- Create a column that computes \hat{y} , keeping the coefficients as separate cells
- Compute the sum of squares of the residuals (another column, sum the results)
- Use the solver to minimize this sum, modifying the coefficient cells
- Note: regression in Excel + display equation is dangerous if you choose the 'line' plot (use scatter if you can)



How good is the model?



- For a model to make sense the data points should be scattered randomly around the model predictions, the mean of the residuals d should be zero: $d_i = (y_i \hat{y}_i)$
- It's always good to check if the residuals are not correlated with the measured values, if that is the case, it can indicate that your model is wrong.



Today's outline

- Introduction
- Curve fitting
- Regression
- Fitting numerical models
- Optimization
- Linear programming
- Summary



Regression coefficients

Variance measured in the data (y) is:

$$\sigma_y^2 = \frac{1}{N} \sum_i (y_i - \overline{y})^2$$

• Variance of the residuals is:

$$\sigma_{\mathsf{error}}^2 = \frac{1}{N} \sum_{i} (d_i)^2$$

• Variance in the model is:

$$\sigma_{\mathsf{model}}^2 = \frac{1}{N} \sum_{i} \left(\hat{y}_i - \overline{\hat{y}} \right)^2$$



Regression coefficients

Given that the error is uncorrelated we can state that:

$$\sigma_{\rm y}^2 = \sigma_{\rm error}^2 + \sigma_{\rm model}^2$$

$$R^2 = \frac{\sigma_{\text{model}}^2}{\sigma_y^2} = 1 - \frac{\sigma_{\text{error}}^2}{\sigma_y^2}$$

$$R^2 = 1 - \frac{\text{SSE}}{\text{SST}}$$


- SSE: Sum of errors squared
- SST: Total sum of squares (model)
- SSR: Sum of squares (data)



Back to the example

The statistics:

	Value
Ν	100
SSE	32.042
SST	896.907
SSR	928.950
R^2	0.964





Today's outline

- Introduction
- Curve fitting
- Regression
- Fitting numerical models
- Optimization
- Linear programming
- Summary



Curve fitting from commandline: Isqcurvefit

Matlab offers various non-linear parameter and curve fitting tools that can be run from the commandline. The function <code>lsqcurvefit</code> allows to fit a model to a given dataset. Again, based on the data generated in slide 345:

```
% Initial guess of coefficients
a0 = [1 2 1 3];

% Perform fitting, store resulting coeffs in a_fit
a_fit = lsqcurvefit(@curve_fit_model, a0, x, y)

% Run the model once more, with fitted coefficients
y_model = curve_fit_model(a_fit, x);
plot(x,y_model, '-r')
```

We just need a function that captures the model that we want to fit. This can be an inline function or a separate file:

```
function [y] = curve_fit_model(a,xdata)
y = a(1)*xdata.^3+a(2)*xdata.^2 + a(3)*xdata + a(4);
end
```



Dynamic fitting of non-linear equations: Isqnonlin

You may encounter situations where the model data is slightly more complicated to obtain (e.g. a numerical model based on ODEs where coefficients are unknown), or you want to perform fitting of multiple functions/coefficients, or just want to automate things via scripts. Matlab's Optimization toolbox gives access to a powerful function <code>lsqnonlin</code>, least-squares non-linear optimization.



General use of Isqnonlin

```
k = lsqnonlin(fun,k0,lb,ub,options)
```

- fun is a function handle to the fit criterium (e.g. @myFitCrit). The fit criterium function myFitCrit should return the residuals vector, e.g. $d_i = (y_i \hat{y}_i)$. Here, y_i would again be the measurement data and \hat{y} the solution computed by a model.
- ko is the initial guess for the fitting coefficient (or: array of initial guesses when fitting multiple coefficients)
- 1b and ub are the lower and upper boundaries for k0. These should both be the size of the k0-array.
- options are some fitting options, for more fine-grained control on the fit procedure. Use
 e.g. options = optimset('TolX',1.0E-6,'MaxFunEvals',1000); to create an options object, or leave
 it empty (options = []).



Example use of Isqnonlin

We have experimental data stored in the file tudataset1.mat, containing T and U data. We want to fit a model with coefficients k_1 and k_2 with the following structure:

$$\frac{du}{dt} = -k_1 u + k_2$$

• First, we need to create a function that contains the ODE:

```
function dudt = simpleode(t,u,k);
dudt = -k(1)*u + k(2);
```

Note that we supply a vector k, containing both coefficients for fitting

• We create a fit criterium function:

```
function err = fitcrit(ke,T,U,U0)
[t,ue] = ode45(@simpleode,T,U0,[],ke);
err = (ue-U);
```



roduction Curve fitting Regression Fitting numerical models Optimization Linear programming Summary


Example use of Isqnonlin

Now let's make a script that uses lsquonlin to yield k-values fitted to our dataset:

Our fitted coefficients are stored in ke. Note that we get a lot more data back that allows to check the fitting results in more detail.



Example use of Isqnonlin





Postprocessing of results

The data returned by <code>lsqnonlin</code> can be used to obtain the 95% confidence intervals. Recall the command:

Using the residuals and Jacobian we can use nlparci to get the confidence bounds:

```
cflim = nlparci(ke, RESIDUAL, JACOBIAN);

clc
disp('model parameters and confidence limits');
T = table;
T.ke = ke';
T.LowerCI = cflim(:,1);
T.UpperCI = cflim(:,2)
```



Second example: Isqnonlin

The model does not have to be an ODE. It can be any model that is part of the fitting goal function. Let's consider an (adapted) version of the Laplace equation solver, where we can set a single, central node to a certain temperature:

```
function T = solveLaplaceEq(Nx,Ny,Tb,Tint)
% Solves the Laplace equation for steady-state heat conduction
e = ones(Nx*Nv.1):
A = spdiags([e,e,-4*e,e,e],[-Nx,-1,0,1,Nx],Nx*Ny,Nx*Ny);
b = zeros(Nx*Nv.1):
                                     % Right hand side vector
[A,b] = setBoundaryConditions(A,b,Tb,Nx,Ny);
% Set a central node to Tint
ind = round(Nx * (Ny/2));  % Find index in center
                          % Reset matrix for boudary cells
A(ind.:) = 0:
A(ind,ind) = 1:
                            % Add a 1 on the diagonal
b(ind) = Tint:
                             % Set rhs to desired T
T = A \setminus b:
```



Second example: Isqnonlin

Now let's make a goal function based on our model and the desired setpoint (the mean temperature in the domain):

```
function [err] = fitcrit_laplace(actuate_T, Nx, Ny, boundary_T, setpoint_T)
% Compute model:
T = solveLaplaceEq(Nx, Ny, boundary_T, actuate_T);
% Compute error (deviation of mean T with desired setpoint T)
err = mean(T,'all') - setpoint_T;
end
```



 Curve fitting
 Regression
 Fitting numerical models
 Optimization
 Linear programming
 Summar

 000000000
 0000
 0000
 0000
 0000
 0000000000
 0

Second example: Isqnonlin

- Set up system parameters
- Run the fitting procedures
- Compute and plot the final solution

```
% Set up parameters
Nx = 35; Ny = 35;
Tb = [40 \ 10 \ 40 \ 10]:
                        % Fixed boundary temperatures
TO = 0:
                        % Initial guess
T set = 20:
                        % Setpoint
UB = Inf: LB = -Inf:
                        % Upper and lower bounds
opts = optimoptions('lsqnonlin', 'Display', 'iter');
% Run fitting
T_fit = lsqnonlin(@(T) fitcrit_laplace(T, Nx, Ny, Tb, T_set), T0, LB, UB, opts)
% Is the same as:
% T_fit = lsgnonlin(@fitcrit_laplace, TO, LB, UB, opts, Nx, Nv, Tb, T_set)
% Compute again and plot
T_model = solveLaplaceEq(Nx, Ny, Tb, T_fit);
T_plot = reshape(T_model,[Nx Ny]);
                                          % Reshape x-vec to mat Nx, Ny
[x,v] = meshgrid(1:Nv,1:Nx):
                                          % Get position arrays
surf(x,y,T_plot)
                                          % Surface plot
mean (T model)
  TECHNOLOGY
```

Today's outline

- Introduction
- Curve fitting
- Regression
- Fitting numerical models
- Optimization
- Linear programming
- Summary



What is optimization?

Optimization is minimization or maximization of an objective function (also called a performance index or goal function) that may be subject to certain constraints.

- $\min f(x)$: Goal function
- g(x) = 0: Equality constraints
- $h(x) \ge 0$: Inequality constraints



Optimization Spectrum

Problem	Method	Solvers
LP	Simplex method Barrier methods	Linprog (Matlab) CPLEX (GAMS, AIMMS, AMPL, OPB)
NLP QP	Lagrange multiplier method Successive linear programming Quadratic programming	Fminsearch/fmincon (Matlab) MINOS (GAMS, AMPL) CONOPT (GAMS)
MIP MILP MINLP MIQP	Branch and bound Dynamic programming Generalized Benders decomposition Outer approximation method Disjunctive programming	Bintprog (Matlab) DICOPT (GAMS) BARON (GAMS)



Factors of concern

- Continuity of the functions
- Convexity of the functions
- Global versus local optima
- Constrained versus unconstrained optima



Today's outline

- Introduction
- Curve fitting
- Regression
- Fitting numerical models
- Optimization
- Linear programming
- Summary



Linear programming

In linear programming the objective function and the constraints are linear functions.

For example:

max
$$z = f(x_1, x_2) = 40x_1 + 88x_2$$


s.t. (subject to)
 $2x_1 + 8x_2 \le 60$
 $5x_1 + 2x_2 \le 60$
 $x_1 \ge 0$
 $x_2 \ge 0$

If the constraints are satisfied, but the objective function is not maximized/minimized we speak of a feasible solution.

If also the objective function is maximized/minimized, we speak of an optimal solution!




Plotting the constraints





Plotting the constraints





Normal form of an LP problem

$$\max z = f(x_1, x_2) = 40x_1 + 88x_2$$
s.t.
$$2x_1 + 8x_2 \le 60$$

$$5x_1 + 2x_2 \le 60$$

$$x_1 \ge 0$$

$$x_2 \ge 0$$

max
$$z = f(x) = 40x_1 + 88x_2$$

s.t.
 $2x_1 + 8x_2 + x_3 = 60$
 $5x_1 + 2x_2 + x_4 = 60$
 $x_i \ge 0$ $i \in 1, 2, 3, 4$

x₃ and x₄ are called slack variables, they are non auxiliary variables introduced for the purpose of converting inequalities in to equalities



The simplex method

We can formulate our earlier example to the normal form and consider it as the following augmented matrix with $T_0 = \begin{bmatrix} z & x_1 & x_2 & x_3 & x_4 & b \end{bmatrix}$:

$$T_0 = \begin{bmatrix} 1 & -40 & -88 & 0 & 0 & 0 \\ 0 & 2 & 8 & 1 & 0 & 60 \\ 0 & 5 & 2 & 0 & 1 & 60 \end{bmatrix}$$

This matrix is called the (initial) simplex table. Each simplex table has two kinds of variables, the basic variables (columns having only one nonzero entry) and the nonbasic variables



The simplex method

$$T_0 = \begin{bmatrix} 1 & -40 & -88 & 0 & 0 & 0 \\ 0 & 2 & 8 & 1 & 0 & 60 \\ 0 & 5 & 2 & 0 & 1 & 60 \end{bmatrix}$$

Every simplex table has a feasible solution. It can be obtained by setting the nonbasic variables to zero: $x_1 = 0$, $x_2 = 0$, $x_3 = 60/1$, $x_4 = 60/1$, z = 0.



The optimal solution?

- The optimal solution is now obtained stepwise by pivoting in such way that z reaches a maximum.
- The big question is, how to choose your pivot equation ...



Step 1: Selection of the pivot column

Select as the column of the pivot, the first column with a negative entry in Row 1. In our example, that's column 2 (-40)

$$T_0 = \begin{bmatrix} 1 & -40 & -88 & 0 & 0 & 0 \\ 0 & 2 & 8 & 1 & 0 & 60 \\ 0 & 5 & 2 & 0 & 1 & 60 \end{bmatrix}$$



Step 2: Selection of the pivot row

Divide the right sides by the corresponding column entries of the selected pivot column. In our example that is 60/2 = 30 and 60/5 = 12.

$$T_0 = \begin{bmatrix} 1 & -40 & -88 & 0 & 0 & 0 \\ 0 & 2 & 8 & 1 & 0 & 60 \\ 0 & 5 & 2 & 0 & 1 & 60 \end{bmatrix}$$

Take as the pivot equation the equation that gives the smallest quotient, so 60/5.



Step 3: Elimination by row operations

- Row 1 = Row 1 + 8 * Row 3
- Row 2 = Row 2 0.4 * Row 3

$$T_1 = \begin{bmatrix} 1 & 0 & -72 & 0 & 8 & 480 \\ 0 & 0 & 7.2 & 1 & -0.4 & 36 \\ 0 & 5 & 2 & 0 & 1 & 60 \end{bmatrix}$$

The basic variables are now x_1 , x_3 and the nonbasic variables are x_2 , x_4 . Setting the nonbasic variables to zero will give a new feasible solution: $x_1 = 60/5$, $x_2 = 0$, $x_3 = 36/1$, $x_4 = 0$, z = 480.



The simplex method

- We moved from z = 0 to z = 480. The reason for the increase is because we eliminated a negative term from the equation, so: elimination should only be applied to negative entries in Row 1, but no others.
- Although we found a feasible solution, we did not find the optimal solution yet (the entry
 of -72 in our simplex table) → repeat step 1 to 3.



The simplex method

Another iteration is required:

- Step 1: Select column 3
- Step 2: 36/7.2 = 5 and $60/2 = 30 \longrightarrow \text{select } 7.2$ as the pivot
- Elimination by row operations:
 - Row 1 = Row 1 + 10 *Row 2
 - Row 3 = Row 3 (2/7.2) *Row 2

$$T_2 = \begin{bmatrix} 1 & 0 & 0 & 10 & 4 & 840 \\ 0 & 0 & 7.2 & 1 & -0.4 & 36 \\ 0 & 5 & 0 & -1/36 & 1/0.9 & 50 \end{bmatrix}$$

• The basic feasible solution: $x_1 = 50/5$, $x_2 = 36/7.2$, $x_3 = 0$, $x_4 = 0$, z = 840 (no more negative entries: so this solution is also the optimal solution)



Using Matlab for LP problems

We are going to solve the following LP problem: $\min f(x) = -5x_1 - 4x_2 - 6x_3$ s.t. $x_1 - x_2 + x_3 \le 20$ $3x_1 + 2x_2 + 4x_3 \le 42$ $3x_1 + 2x_2 \le 30$ $x_1 \ge 0$ $x_2 \ge 0$

Using the function linprog:

```
f = [-5; -4; -6]
A = [1 -1 1; 3 2 4; 3 2 0];
b = [20; 42; 30];
lb = zeros(3,1);
[x,fval,exitflag,output,lambda]
= linprog(f,A,b,[],[],lb);
```

Gives:

```
x = 0.00 15.00 3.00
lambda.ineqlin = 0 1.50 0.50
lambda.lower = 1.00 0 0
```



 $x_3 \ge 0$



- Curve fitting: Manual procedures for polynomial fitting in Matlab
- Curve fitting: Matlab's curve-fitting toolbox
- Curve fitting: Matlab's non-linear least-squares solver lsqnonlin
- Optimization: An introduction to the Simplex method
- Optimization: Use of the lingrog solver

