
ME1306 Dynamometer Plot



Torque in Pound Inches

Notes:

- 1) Efficiency is the System Efficiency that includes the Motor Control losses.
- Plot taken with DC Power Supply as the input.
- 3) Higher load performance can be estimated by noting that these are linear functions.