

Mitsubishi Electric PUZ-ZM250 heat pump error code U4 defrost thermistor

Commissioning: pressure test with nitrogen then evacuate to 500 microns

