



Document Number: SCN074278

Revision: A

Group: Scanned (Hardcopy) Item

Type: Environmental Reports - Svs Ctr

State: Released


Latest Released: YES


Implemented Date: 03/20/2020


Stamp Date: Friday, March 20, 2020 7:55:49 AM EST


viewLinc Location History Report


Report name	ETHICON Quarterly Report
Location history	from 2019-10-01 12:00:00 to 2020-01-01 12:00:00
Report generated on	2020-01-01 12:00:20 (UTC-05:00) Eastern Time (US & Canada)
Include trend graphs:	Yes
Include threshold lines on graphs:	Yes
Include zones and locations:	System/ETHICON
Include report summary tables:	Yes
Include real-time values:	No
Include device samples:	No
Include statistics tables:	No
Include summary statistics:	Yes
Include interval statistics tables:	No
Include interval statistics graphs:	No
























Page 10 of 13





Summary for %RH locations	is			
#		2	ω	4
Plot Legend:				
Location:	Receiving&Decontamination RH (11912)	Repair & Testing RH (11918)	Repair & Testing2 RH (11922)	Spare parts & Shippi (11926)
Zone:	System/ETHICON (11911)	System/ETHICON (11911)	System/ETHICON (11911)	System/ETHICON (1
Units:	%RH	%RH	%RH	%RH
Device Serial Number:	17332041	17332042	17332036	17332040
Hardware Model:	2000 35R VL	2000 35R VL	2000 35R VL	2000 35R VL
Hardware Revision:	6.13	6.13	6.13	6.13
Firmware Version:	3.39.1	3.39.1	3.39.1	3.39.1
Security:	Secure	Secure	Secure	Secure
Last Calibrated By:	Vaisala Inc.	Vaisala Inc.	Vaisala Inc.	Vaisala Inc.
Last Calibration Date:	2019-09-18	2019-09-18	2019-09-18	2019-09-18
Next Calibration Date:	2020-09-18	2020-09-18	2020-09-18	2020-09-18
Host:	ITSUSRAWSP04243.jnj.com	ITSUSRAWSP04243.jnj.com ITSUSRAWSP04243.jnj.com ITSUSRAWSP04243.jnj.com ITSUSRAWSP0424	ITSUSRAWSP04243.jnj.com	ITSUSRAWSP04243
Summary for %RH locations	าร			
#	G			
Plot Legend:				
Location:	Warehouse RH (11928)			
Zone:	System/ETHICON (11911)			
Units:	%RH			
Device Serial Number:	17332038			
Hardware Model:	2000 35R VL			
Hardware Revision:	6.13			
Firmware Version:	3.39.1			
Security:	Secure			
Last Calibrated By:	Vaisala Inc.			
Last Calibration Date:	2019-09-18			
Next Calibration Date:				
	2020-09-18			

Plot Legend:

Location:

Zone:

System/ETHICON (11911) Receiving&Decontamination T (11914)

System/ETHICON (11911)

System/ETHICON (11911)

System/ETHICON (11911)

Spare parts & Shipping T (11924)

9

Repair & Testing2 T (11920)

Repair & Testing T (11916)

Device Serial Number:

Summary for °F locations

Time zone: (UTC-05:00) Eastern Time (US & Canada)	Service Manager Name: Eric Smith Date: 03-17-2026 Signature:

Security: Last Calibrated By:	3.39.1 Secure Vaisala Inc.
Last Calibrated By:	Vaisala Inc.
Last Calibration Date:	2019-09-18
Next Calibration Date:	2020-09-18
Host:	ITSUSRAWSP04243.jnj.cor

#	10
Plot Legend:	
Location:	Warehouse T (11930)
Zone:	System/ETHICON (11911)
Units:	ñ
Device Serial Number:	17332038
Hardware Model:	2000 35R VL
Hardware Revision:	6.13
Firmware Version:	3.39.1
Security:	Secure
Last Calibrated By:	Vaisala Inc.
Last Calibration Date:	2019-09-18
Next Calibration Date:	2020-09-18
Host:	ITSUSRAWSP04243.jnj.com

Summary for °F locations

Last Calibrated By:

Next Calibration Date: Last Calibration Date: Security:

Firmware Version: Hardware Revision: Hardware Model:

3.39.1 6.13

3.39.1 6.13

Secure

Vaisala Inc.

Vaisala Inc.

Vaisala Inc. Secure

Secure

3.39.1 6.13

2019-09-18

2020-09-18

2000 35R VL 17332041

2000 35R VL 17332042

6.13 3.39.1

2000 35R VL

2000 35R VL

17332040

17332036

Secure Vaisala Inc.

2019-09-18

2020-09-18

ITSUSRAWSP04243.jnj.com ITSUSRAWSP04243.jnj.com ITSUSRAWSP04243.jnj.com ITSUSRAWSP04243.jnj.com

2020-09-18 2019-09-18

2020-09-18 2019-09-18

Quality Lead Name: Robert Peters Date: 3/10/2020 Signature:

Security Status: Secure

Signature: Name: Ibrahim Bitar Date: 03-04-2020

Page 13 of 13

VEMS Administrator