

Repeat-indication engineering context

SIM-ENG-21-R1 | Revision 1 | ENGINEERING_NOTE

Operator SIM-AIR | A350-900 | CAB-C01 | Station ALL

Status ACTIVE | Trust TRUSTED | Effective 2026-09-01 to 2027-09-01

1. Purpose

SIMULATION ONLY. Original fictional planning document. Not an OEM manual, approved MEL, maintenance instruction, flight-safety assessment or release authorization. Historical recurrence is context for investigation, not a diagnosis.

2. Known record

HIST-0042 / WO-0042 on AC-001 is recorded 42 days before this scenario. The summary reports correction of an indication connection issue without component replacement.

3. Caution

Compare symptom wording, aircraft configuration and prior findings. No-fault-found records do not establish that the present aircraft is serviceable. Present both matching and conflicting history to the engineer.