

Pre-arrival cabin-zone indication planning brief

SIM-PROC-21-R3 | Revision 3 | PLANNING

Operator SIM-AIR | A350-900 | CAB-C01 | Station ALL

Status ACTIVE | Trust TRUSTED | Effective 2026-09-01 to 2027-09-01

1. Purpose

SIMULATION ONLY. Original fictional planning document. Not an OEM manual, approved MEL, maintenance instruction, flight-safety assessment or release authorization. For event DEMO-A350-21-047, assemble evidence for ground inspection. Indication intermittency is the reported symptom, not a confirmed root cause.

2. Information to prepare

Collect event timestamps, affected indication group, crew narrative, existing defects and recent work orders. Do not infer continued-flight safety from this material.

3. Resources

SIM-TASK-001 requires task scope SIM-CABIN-COMFORT, a matching current operator authorization and in-calibration SIM-DIAG-CAB tooling. Resource labels are fictional.

4. Part contingency

DEMO-CZT-100 is a contingency candidate only. A previous connection-related finding is not proof that a new event needs the same action or that replacement is unnecessary.

5. Planning times

Fixture assumptions: 15 minutes inspection, 10 minutes resolution, 10 minutes verification and 5 minutes recording. Replacement path uses a 75-minute complete work-package assumption. These are not maintenance labor standards.

6. Decision boundary

Authorized personnel must select and follow the real current task in any operational deployment. This document intentionally supplies no physical repair steps, test values, resets or wiring instructions.