

SIMULATION ONLY

Historical work package WO-0042

SIM-WO-0042-R1 | Revision 1 | HISTORICAL

Operator SIM-AIR | A350-900 | CAB-C01 | Station ALL

Status ACTIVE | Trust TRUSTED | Effective 2026-09-01 to 2027-09-01

1. Scope

SIMULATION ONLY. Original fictional planning document. Not an OEM manual, approved MEL, maintenance instruction, flight-safety assessment or release authorization.

2. Record

Aircraft AC-001; previous case HIST-0042; station FRA; event DEMO-A350-21-047. The historical symptom was cabin-zone temperature indication intermittency.

3. Outcome

The completed record reports an indication connection issue corrected without component consumption. That record is evidence of what happened previously, not an instruction or prediction for the new case.