

SENTINEL — ANOMALY REPORT

Unauthorized Construction

ANO-0007

SEVERITY	STATUS	CONFIDENCE
MODERATE	UNRESOLVED	51.7%
COORDINATES	0.1074° N, 0.0000° E	
REGION	CSV Dataset	
TIMESTAMP	2026-04-27 05:55 UTC	

Progressive structural change detected in a no-build zone. Footprint expansion identified.