

Mine Citation/Order

U.S. Department of Labor
Mine Safety and Health Administration

Section I--Violation Data

1. Date	Mo Da Yr 10/8/2024	2. Time (24 Hr. Clock) 1055	3. Citation/ Order Number 9783475
4. Served To	Ray Hood		5. Operator PEABODY GATEWAY NORTH MINING, LLC
6. Mine	GATEWAY NORTH MINE		7. Mine ID 11-03235 (Contractor)
8. Condition or Practice	8a. Written Notice (103g) <input type="checkbox"/>		

The circuit breaker and receptacle on Transformer Co. #979 were not marked for identification for the Fletcher Roof Bolter Co. #410 located in Unit #1, MMU-011. The identifying tags were located on the 480 volt circuit #9 and the Roof Bolter was connected to circuit #10. This hazard exposes miners to electrical shock type injuries.

Standard 75.904 was cited 5 times in two years at mine 1103235 (5 to the operator, 0 to a contractor).

See Continuation Form (MSHA Form 7000-3a)

9. Violation	A. Health <input type="checkbox"/> Safety <input checked="" type="checkbox"/> Other <input type="checkbox"/>	B. Section of Act	C. Part/Section of Title 30 CFR 75.904
--------------	--	-------------------	--

Section II--Inspector's Evaluation

10. Gravity:							
A. Injury or Illness (has) (is):	No Likelihood <input type="checkbox"/>	Unlikely <input type="checkbox"/>	Reasonably Likely <input checked="" type="checkbox"/>	Highly Likely <input type="checkbox"/>	Occurred <input type="checkbox"/>		
B. Injury or illness could reasonably be expected to be:	No Lost Workdays <input type="checkbox"/>		Lost Workdays Or Restricted Duty <input type="checkbox"/>	Permanently Disabling <input type="checkbox"/>	Fatal <input checked="" type="checkbox"/>		
C. Significant and Substantial:	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	D. Number of Persons Affected: 001				
11. Negligence (check one)	A. None <input type="checkbox"/>	B. Low <input checked="" type="checkbox"/>	C. Moderate <input type="checkbox"/>	D. High <input type="checkbox"/>	E. Reckless Disregard <input type="checkbox"/>		
12. Type of Action	104 (a)	13. Type of Issuance (check one)		Citation <input checked="" type="checkbox"/>	Order <input type="checkbox"/>	Safeguard <input type="checkbox"/>	Written Notice <input type="checkbox"/>
14. Initial Action	A. Citation <input type="checkbox"/>	B. Order <input type="checkbox"/>	C. Safeguard <input type="checkbox"/>	D. Written Notice <input type="checkbox"/>	E. Citation/ Order Number	F. Dated	Mo Da Yr
15. Area or Equipment							

16. Termination Due	A. Date 10/8/2024	Mo Da Yr	B. Time (24 Hr. Clock) 1115	
---------------------	----------------------	----------	--------------------------------	--

Section III--Termination Action

17. Action to Terminate
The circuit breaker and the receptacle were properly identified.

18. Terminated	A. Date 10/8/2024	Mo Da Yr	B. Time (24 Hr. Clock) 1100	
----------------	----------------------	----------	--------------------------------	--

Section IV--Automated System Data

19. Type of Inspection (activity code)	E01	20. Event Number F005A35	21. Primary or Mill	
22. AR Name	Brandon Lampley		23. AR Number 25374	

MSHA Form 7000-3, Apr 08 (revised) In accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudsman and 10 Regional Fairness Boards to receive comments from small businesses about federal agency enforcement actions. The Ombudsman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd Street, SW MC 2120, Washington, DC 20416. Please note, however, that your right to file a comment with the Ombudsman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.