

SERVICE FEEDBACK NOTE (SFN)



To : HTA-Engineering 11 Reference No : SFN/MWRWAC/19/000559

Designation : Engineer Date : 25-Feb-2019 12:42

Department : L3GL2 Location : Sample Preparation Room (IEM Department)

We are not able to complete the required service within 7 days due to the problem as listed below:-

ASSET DETAILS	
ASSET NO.	WB326006019A
ASSET NAME	Stirrers
WORK ORDER NO.	MWRWAC/19/000559
SERVICE REQUEST DESCRIPTION	B-HOT PLATE TEMPERATURE (L3-GL-015)