SAFETY ALERT: Beedome baby cot

Date of notice

27 June 2025

Name of product

Beedome baby cot

Product picture



Sample taken from

Seller "tteynliu619 [1] .sg" on Shopee

The Consumer Product Safety Office has issued a notice to tteynliu619 [1] .sg to cease supply of the baby cot.

During the testing of this sample, it was found that the product did not comply with the following requirements from EN 716-1:2017 "Furniture - Children's cots and folding cots for domestic use":

- Self-tapping screws were found to be used to fasten components that are designed to be removed or loosened when dismantling the cot for purposes of transportation or storage. These screws can gradually loosen over time, posing a potential fall risk to the baby.
- There were gaps, shear and squeeze points on the baby cot that can pose an entrapment risk to the baby's body parts such as the fingers and limbs.
- Parts of the sides and ends of the cot had snag points sufficiently high above the cot base to pose a strangulation risk to a baby from potential snagging of clothes or loops formed by items carried by the baby.
- Parts of the cot base broke under an impact that is similar to the weight of a baby, posing a fall risk to a baby from potential collapse of the cot base.
- When the movable side was adjusted to its highest position, the locking system did not automatically engage, which can pose an entrapment risk to a baby's body.

- When the mattress base was positioned in the lowest position, the upper side of the mattress base was too close to the upper edge of the cot side, which can allow a baby to potentially climb out of the cot and fall. In addition, there were footholds close enough to the top rail of the cot that could allow a baby to climb out of the cot and fall.
- The cot slats broke when subjected to a force that babies can reasonably exert, posing a risk of injury to the baby from the broken parts. In addition, it was found that a baby could exit the cot from the opening, posing a fall risk.
- The instructions and warnings provided were not in accordance with the requirements (e.g., content, format, language).

No report of incident or injury related to the use of this product has been received to date. Consumers who have bought the product are advised to stop using it immediately.