## Yamaha Corporation Recalls AC Power Adaptor PA-300C

Yamaha Corporation has issued a voluntary recall for the PA-300C AC adaptor used with various Digital Piano models, and also sold separately as accessories. The DC plug may generate abnormal heat, potentially leading to melting, smoke, or ignition causing the DC plug to short circuit.

## **Affected Products:**

- 1. Individually Sold PA-300C Adaptors
  - Serial Numbers: XXXX0XXXXXX to XXXX25XXXXX
- 2. Piano models with Included PA-300C Adaptors:
  - DTX900/DTX900M
  - ICP1
  - MOTIF-RACK XS
  - UR824
- 3. Piano models with Built-in PA-300C Adaptors:
  - CLP-430 series (B/C/M/PE/R/WH models)
  - CVP-601 series (B/PE models)



Consumers should immediately stop using the affected adaptor, and disconnect it from both the mains outlet as well as the product. Please contact Yamaha Service Center for a complimentary exchange.

## **Contact Information:**

Yamaha Music (Asia) Private Limited – Service Center 6 Changi South Street 2 #01-02 Xilin District Center Building D Singapore 486349

- Service Helpdesk: 67409262

- WhatsApp: 84748684

- Email: service-SGP@music.yamaha.com

Yamaha is offering free home delivery/replacement or self-collection options at their Service Centre. Customers must provide the original adapter during the exchange process.

For detailed serial number verification and additional information, please visit Yamaha's support website.