SAFETY ALERT: Hashengxiong HSX 002 baby bouncer

Date of notice

9 September 2024

Name of product

Hashengxiong HSX 002 baby bouncer

Product picture



Sample taken from

Seller "Unk.sg" on Shopee

The Consumer Product Safety Office has issued a notice to Unk.sg to cease supply of the baby bouncer.

During the testing of this sample, it was found that the product did not comply with the following requirements from ASTM F2167-22 Standard Consumer Safety Specification for Infant Bouncer Seats:

- Small parts (including warning labels) were easily detachable from the baby bouncer and could pose a choking hazard.
- The restraint system of the baby bouncer could break easily when holding a baby and could pose accident risks.
- The baby bouncer did not meet the slip resistance requirements, which could lead to fall risks.

 The bouncer can be lifted off the ground by the toy bar which could detach while carrying a baby, posing fall risks.
- The instruction and warnings provided were not in accordance with the requirements (e.g. content, format, language).

No report of incident or injury related to the use of this product has been received to date. Consumers who have bought the product are advised to stop using it immediately.