SAFETY ALERT: Mas Baby 309 baby bouncer with wheels

Date of notice

9 September 2024

Name of product

Mas Baby 309 baby bouncer with wheels

Product picture



Sample taken from Seller "Baby's Hyperstore" on Shopee

The Consumer Product Safety Office has issued a notice to Baby's Hyperstore to cease supply of the baby bouncer.

During the testing of this sample, it was found that the product did not comply with the following requirements from ASTM F2167-22 Standard Consumer Safety Specification for Infant Bouncer Seats:

- Small parts and protective components were easily detachable from the baby bouncer and could pose a choking hazard.
- The restraint system of the baby bouncer could break easily when holding a baby and could pose accident risks.
- The baby bouncer did not meet the slip resistance requirements, which could lead to fall risks.
- Moving parts of the baby bouncer could injure a baby through shearing or pinching.
- The baby bouncer has small gaps and openings in which a baby could get their fingers stuck, causing injury.
- The baby bouncer has no latching or locking mechanisms to prevent unintentional folding, which could lead to suffocation and fall risks to a baby.
- The instruction and warnings provided were not in accordance with the requirements (e.g. content, format, language).

No report of incident or injury related to the use of this product has been received to date. Consumers who have bought the product are advised to stop using it immediately.