




Magnetic coupled DCDC converter



Cancellation of DC flux with M12
Voltage generation due to leakage inductance
(High magnetic resistance)
->High powered DCDC converter with small inductor

Mitigate ripple current with interleaved switching



Using leakage inductance(varies depending on current value) ->Linier model of inductor can not be used.
3D CAE -> Converter operation analysis is difficult or very high load in calculation.

